



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

February 13, 2015

Mr. Phillip Ownbey
President & Chief Operating Officer
Morgan Olson Corporation
1801 S. Nottawa Street
Strugis, MI 49091

NVS-215KS
15V-065

Subject: Rear Vehicle Illumination Incorrect/FMVSS 108

Dear Mr. Ownbey:

This letter serves to acknowledge Morgan Olson Corporation's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

MORGAN OLSON/SERVICE BODY/2014

Mfr's Report Date: February 3, 2015

NHTSA Campaign Number: 15V-065

Components:

EXTERIOR LIGHTING

Potential Number of Units Affected: 11

Problem Description:

Morgan Olson Corporation (Morgan Olson) is recalling certain model year 2014 Service Body trucks built on Sprinter cab chassis manufactured April 11, 2014, to December 18, 2014. The affected vehicles may have the rear identification lamps mounted below the doors. Also, the license plate illumination lamp may be mounted incorrectly which may result in incomplete illumination of the license plate. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) No. 108, "Lamps, Reflective Devices, and Associated Equipment."

Consequence:

If the rear identification lamps and the license plate lamp are not mounted correctly, the vehicle may have reduced visibility, increasing the risk of a vehicle crash.

Remedy:

Morgan Olson will notify owners, and dealers will modify the trucks to add rear identification lights above the door, and remount the license plate lamp, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Morgan Olson customer service at 1-800-262-3437.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



Please be reminded of the following requirements:


You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As required in Part 573.6(c)(7), in the case of a noncompliance, please provide the date of the engineering review used to determine the existence of the noncompliance. Please provide this information as soon as possible.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Kelly Schuler who may be reached by phone at (202) 366-5227, or by email at kelly.schuler@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

A handwritten signature in black ink, appearing to read "Jennifer Timian". The signature is fluid and cursive, with a long horizontal stroke at the end.

Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement