

U.S. Department of Transportation

National Highway Traffic Safety Administration

July 31, 2015

Mr. David Robertson Group Manager, Environmental, Safety and Powertrain Engineering Mazda North American Operations 1025 Connecticut Ave, NW Washington, DC 20036 NVS-215SM 15V-451

1200 New Jersey Avenue SE Washington, DC 20590

Subject: Corrosion of Front Suspension Ball Joint

Dear Mr. Robertson:

This letter serves to acknowledge Mazda North American Operations's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

MAZDA/CX-9/2007-2014

Mfr's Report Date: July 16, 2015

NHTSA Campaign Number: 15V-451

Components:

SUSPENSION:FRONT:CONTROL ARM:LOWER ARM SUSPENSION:FRONT:CONTROL ARM:LOWER BALL JOINT

Potential Number of Units Affected: 193,484

Problem Description:

Mazda North American Operations (Mazda) is recalling certain model year 2007-2014 CX-9 vehicles manufactured October 24, 2006, to December 28, 2013. The affected vehicles have front suspension ball joints that may corrode from water leaking into the fitting.

Consequence:

Over time, the ball joint corrosion may result in the front lower control arm separating from the ball joint, causing a loss of steering control and increasing the risk of a crash.

Remedy:

Mazda will notify owners, and dealers will replace both the left and right lower control arms, free of charge. In early September 2015, owners will be mailed an interim notification informing them of recall. When remedy parts are available, owners will be mailed a second notification. The recall will begin with model year 2007-2009 vehicles registered in Connecticut, Delaware, Illinois, Indiana, Iowa, Kentucky, Maine, Maryland, Massachusetts, Michigan, Minnesota, Missouri, New Hampshire, New Jersey, New York, Ohio, Pennsylvania, Rhode Island, Vermont, Virginia, Washington D.C., West Virginia, and Wisconsin. The second phase will be for model year 2010-2014 vehicles in the same states. Finally, all remaining vehicles will be remedied. Owners may contact Mazda customer service at 1-800-222-5500. Mazda's number for this recall is 8515G.



Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

This recall was the subject of a preliminary evaluation, PE15-022, conducted by the Office of Defects Investigation.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Sarah Mcshane who may be reached by phone at 202-366-7401, or by email at sarah.mcshane@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian

Chief, Recall Management Division Office of Defects Investigations

Enforcement

