



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

December 24, 2015

Mr. Todd Fronckowiak
Assistant Director, Global Automotive Safety Compliance
Ford Motor Company
Fairlane Plaza South, Suite #500
330 Town Center Drive
Dearborn, MI 48126-2738

NVS-215SM
15V-812

Subject: Fuel Delivery Module may Crack and Leak

Dear Mr. Fronckowiak:

This letter serves to acknowledge Ford Motor Company's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

FORD/EXPLORER/2013
FORD/FLEX/2013
FORD/POLICE INTERCEPTOR SEDAN/2013
FORD/POLICE INTERCEPTOR UTILIT/2013
FORD/TAURUS/2013
LINCOLN/MKS/2013
LINCOLN/MKT/2013

Mfr's Report Date: December 1, 2015

NHTSA Campaign Number: 15V-812

Components:

FUEL SYSTEM, GASOLINE

Potential Number of Units Affected: 868

Problem Description:

Ford Motor Company (Ford) is recalling certain model year 2013 Explorer, Explorer Police Utility, Taurus, Taurus Police Interceptor, Flex, Lincoln MKS, and Lincoln MKT vehicles. In the affected vehicles, the fuel delivery module may crack, allowing fuel to leak.

Consequence:

A fuel leak in the presence of an ignition source may result in a fire.

Remedy:

Ford will notify owners, and dealers will replace the fuel delivery module, free of charge. The recall is expected to begin in December 2015. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 13S04-S1.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

NHTSA has received Ford's draft owner notification letter and has approved it for distribution.

Per the requirements of 573.6(c)(2)(iv), please provide the supplier name, contact information, address and country of origin (if known) for the fuel delivery module.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Sarah Mcshane who may be reached by phone at 202-366-7401, or by email at sarah.mcshane@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,



Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement