## OMB Control No.: 2127-0004

## **Recall Quarterly Report**

15V-098

Manufacturer Name: Toyota Motor Engineering & Manufacturing

NHTSA Recall No. / MFR Recall No.: 15V-098 / Recall Subject: Improperly Tightened Rear Axle Bolts Owner Notification Beginning Date: APR 03, 2015

Owner Notification End Date: APR 03, 2015



Report	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	JUL 27, 2015	2015-3	226	0	0	0
1	JUL 27, 2015	2015-2	226	169	0	0

This Document Last Updated: JUL 29, 2015

## **Definitions:**

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the  $3^{rd}$  quarter of 2012). Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.