

**Recall Quarterly Report****15V-268**

**Manufacturer Name :** Ducati North America  
**NHTSA Recall No. / MFR Recall No. :** 15V-268 /RCL-15-002  
**Recall Subject :** Shock Absorber Damping Rod Nut may Loosen/Detach  
**Owner Notification Beginning Date :** JUN 29, 2015  
**Owner Notification End Date:** JUN 29, 2015



| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|----------------|-------------------|----------------|-------------------|---------------|
| 5        | JUL 22, 2016    | 2016-2         | 549               | 359            | 28                | 0             |
| 4        | APR 27, 2016    | 2016-1         | 549               | 318            | 28                | 0             |
| 3        | JAN 08, 2016    | 2015-4         | 549               | 284            | 27                | 0             |
| 2        | OCT 22, 2015    | 2015-3         | 549               | 228            | 27                | 0             |
| 1        | JUL 28, 2015    | 2015-2         | 549               | 35             | 8                 | 0             |

This Document Last Updated : JUL 25, 2016

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.