

**Recall Quarterly Report****15V-674****Manufacturer Name :** Mazda North American Operations**NHTSA Recall No. / MFR Recall No. :** 15V-674 /8715J**Recall Subject :** Ignition Switch may Overheat**Owner Notification Beginning Date :** DEC 17, 2015**Owner Notification End Date:** DEC 21, 2015

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
6	APR 28, 2017	2017-1	1,368,500	8,332	365,239	19,606
5	JAN 30, 2017	2016-4	1,368,500	8,045	365,041	19,498
4	OCT 30, 2016	2016-3	1,368,500	7,528	364,951	19,338
3	JUL 27, 2016	2016-2	1,368,500	6,296	362,752	19,056
2	APR 27, 2016	2016-1	1,368,500	1,470	198,796	17,307
1	JAN 24, 2016	2015-4	1,368,500	0	0	15,617

This Document Last Updated : MAY 05, 2017

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.