

**Recall Quarterly Report****15V-782**

**Manufacturer Name :** BMW of North America, LLC  
**NHTSA Recall No. / MFR Recall No. :** 15V-782 /  
**Recall Subject :** Driveshaft Slip-Joint may not have been Greased  
**Owner Notification Beginning Date :** JAN 14, 2016  
**Owner Notification End Date:** JAN 14, 2016



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	APR 25, 2016	2016-1	42	37	1	0

This Document Last Updated : MAY 03, 2016

**Definitions :**

- Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).
- Recall Population :** The total number of products recalled by the manufacturer.
- Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.
- Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.
- Total Removed :** Products that have been scrapped, stolen, or exported.