

Part 573 Safety Recall Report**15V-012****Manufacturer Name :** Nissan North America, Inc.**Submission Date :** JAN 14,2015**NHTSA Recall No. :** 15V-012**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Nissan North America, Inc.

Address : P. O. BOX 685001

Franklin TN 37068-5009

Company phone : (999) 999-9999

Population :

Number of potentially involved : 893

Estimated percentage with defect : 0

Vehicle Information :

Vehicle : 2014-2015 Nissan Pathfinder

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : GAS

Descriptive Information : The vehicle population was determined based on an assembly process error.

Production Dates : AUG 14, 2014 - NOV 05, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2014-2015 Nissan Rogue

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : GAS

Descriptive Information : The vehicle population was determined based on an assembly process error.

Production Dates : AUG 12, 2014 - NOV 15, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2014-2015 Infiniti QX60

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The vehicle population was determined based on an assembly process error.

Production Dates : AUG 14, 2014 - NOV 05, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Due to an assembly process issue, the front hub bolts, torque member bolts, and/or stopper bolt may be under torqued or missing. If any of the bolts are not properly tightened, they may loosen and eventually fall off.

Description of the Safety Risk : If left uncorrected over time, the brake caliper may separate from the wheel assembly, reducing braking performance and potentially reducing steering control which could lead to a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : Noise and/or vibration

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

FOREIGN STATES

Country : NR

Chronology :

NR

Description of Remedy :

Description of Remedy Program : Owners of all potentially affected vehicles will be notified to take their vehicle to a Nissan dealer. The dealer will confirm the presence and torque on the front hub bolts, torque member bolts and stopper bolt and tighten any loose nuts to the correct specification, at no cost to the owner.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : JAN 14, 2015 - JAN 14, 2015

Planned Owner Notification Date : FEB 25, 2015 - FEB 25, 2015

* NR - Not Reported