

Part 573 Safety Recall Report**15V-032****Manufacturer Name :** Nissan North America, Inc.**Submission Date :** JAN 23,2015**NHTSA Recall No. :** 15V-032**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Nissan North America, Inc.

Address : P. O. BOX 685001

Franklin TN 37068-5009

Company phone : (999) 999-9999

Population :

Number of potentially involved : 468,815

Estimated percentage with defect : 0

Vehicle Information :

Vehicle : 2008-2013 Nissan Rogue

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : GAS

Descriptive Information : No other Nissan or Infiniti models are affected.

Production Dates : MAR 07, 2007 - NOV 26, 2013

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2014-2014 Nissan Rogue Select

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : GAS

Descriptive Information : No other Nissan or Infiniti models are affected.

Production Dates : SEP 23, 2013 - JUL 02, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : A mixture of snow/water and salt carried onto the driver side floor area (by shoes or other means) can seep into the carpet near the harness connector area and eventually cause an electric short to occur.

Description of the Safety Risk : This short may lead to connector damage, and in rare instances, could potentially cause a thermal incident.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : SUMITOMO ELECTRIC INDUSTRIES, LTD.

Address : 1-3-13, Motoakasaka, Minato-ku,
Tokyo FOREIGN STATES 107-0051

Country : Japan

Chronology :

Nissan is preparing a chronology and will supplement this information shortly.

Description of Remedy :

Description of Remedy Program : Owners of all potentially affected vehicles will be notified to take their vehicle to a Nissan dealer where they will inspect the kick panel wiring harness connector for damage. If no damage is detected, the vehicle will receive a waterproof seal for the harness. If damage is found, the dealer will install a new harness connector and the waterproof seal, all at no cost to the owner.

We will include a statement in the Part 577 owner notification concerning reimbursement for the cost of obtaining a pre-notification remedy for those subject vehicles that are no longer under warranty. Certain newer vehicles are still covered under factory warranty.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Nissan plans to notify dealers on January 23, 2015 and will notify all affected owners within 60 days of DIR submission.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported