

Part 573 Safety Recall Report**15V-034****Manufacturer Name :** BMW of North America, LLC**Submission Date :** JAN 22,2015**NHTSA Recall No. :** 15V-034**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : BMW of North America, LLC

Address : P.O. Box 1227

200 Chestnut Ridge Road Westwood NJ 07675-122

Company phone : 999-999-9999

Population :

Number of potentially involved : 13,130

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2014-2015 MINI Hardtop 2 Door (Cooper trim level)

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : GAS

Descriptive Information : Affected vehicles do not fully conform to FMVSS 110. Approximately 13,130 vehicles are affected.

Production Dates : DEC 01, 2013 - DEC 14, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : This recall involves the vehicle's maximum capacity weight stated on the FMVSS 110 Tire Information Placard. Affected vehicles do not conform to FMVSS 110 Section 4.3(a).

Description of the Safety Risk : The vehicle's maximum capacity weight is incorrect.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

FOREIGN STATES

Country : NR

Chronology :

In mid-November 2014, BMW conducted an engineering evaluation of the Model Year 2014 and 2015 MINI Hardtop 2 Door (Cooper). As part of this evaluation, vehicle capacity weight and the associated Gross Vehicle Weight Rating (GVWR) were assessed. Vehicle development parameters such as weight specifications and chassis dynamics were reviewed as part of this evaluation.

In mid-December, the engineering evaluation led to the realization that the released vehicle capacity weight and associated GVWR were incorrect. Further reviews determined that these values were printed on the respective labels that were used during vehicle production.

On January 14, 2015, BMW determined that certain Model Year 2014 – 2015 MINI Hardtop 2 Door (Cooper) vehicles do not fully conform to FMVSS 110 and 49 CFR 567. As a result, BMW decided to conduct a voluntary recall.

BMW has not received any reports, nor is otherwise aware, of any accidents or injuries related to this issue.

Description of Remedy :

Description of Remedy Program : Affected vehicles will be equipped with an updated FMVSS 110 Tire Information Placard containing the vehicle's correct maximum capacity weight. In addition, affected vehicles will be equipped with an updated Part 567 Certification Label containing the vehicle's correct Gross Vehicle Weight Rating (GVWR).

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : JAN 23, 2015 - MAR 13, 2015

Planned Owner Notification Date : MAR 13, 2015 - MAR 13, 2015

* NR - Not Reported