

Part 573 Safety Recall Report**15V-052****Manufacturer Name :** All Wheel Drive Equipment Mfg., Inc.**Submission Date :** JAN 28,2015**NHTSA Recall No. :** 15V-052**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : All Wheel Drive Equipment Mfg., Inc.

Address : 2022 E. 61st Street North

Tulsa OK 74130

Company phone : 800-311-4778

Population :

Number of potentially involved : 0

Estimated percentage with defect : 0

Vehicle Information :

Vehicle : 2011-2011 FORD F550

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : 2011 FORD F550 #2754

Production Dates : MAY 14, 2010 - MAY 28, 2010

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : MUNCIE FR67 PTOs

Description of the Safety Risk : Over time, oil leaking from the PTO pressure switch onto thermal blanket may cause a fire

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : Muncie Power Products, Inc.

Address : 201 East Jackson Street Ste 500

Muncie FOREIGN STATES 47305

Country : NR

Chronology :

NR

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported