

Part 573 Safety Recall Report**15V-052****Manufacturer Name :** All Wheel Drive Equipment Mfg., Inc.**Submission Date :** MAY 12, 2016**NHTSA Recall No. :** 15V-052**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : All Wheel Drive Equipment Mfg., Inc.

Address : 2022 E. 61st Street North

Tulsa OK 74130

Company phone : 800-311-4778

Population :

Number of potentially involved : 1

Estimated percentage with defect : 1 %

Vehicle Information :

Vehicle 1 : 2011-2011 FORD F550

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : 2011 FORD F550

Production Dates : MAY 14, 2010 - MAY 28, 2010

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : MUNCIE FR67 PTOs

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Over time, oil leaking from the PTO pressure switch onto thermal blanket may cause a fire

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : Muncie Power Products, Inc.
Address : 201 East Jackson Street Ste 500
Muncie 47305
Country : NR

Chronology :

Truck with Muncie part was brought into shop. Was determined this recall would not be an issue since All Wheel Drive installed it differently.

Description of Remedy :

Description of Remedy Program : NR
How Remedy Component Differs from Recalled Component : NR
Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR
Planned Dealer Notification Date : NR - NR
Planned Owner Notification Date : NR - NR

* NR - Not Reported