

Part 573 Safety Recall Report**15V-062****Manufacturer Name :** Newmar Corporation**Submission Date :** MAY 06, 2016**NHTSA Recall No. :** 15V-062**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street

PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

Population :

Number of potentially involved : 30

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2015-2015 Newmar Essex

Vehicle Type :

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : On 2015 Newmar Essex Class A motorhomes, the steering column may have inadequate spline engagement at the steering gear. This could lead to wear and potentially result in the steering shaft becoming disconnected or slipping, causing a loss of steering control and increase the risk of a crash causing injury and/or damage to property.

Production Dates : MAR 13, 2014 - NOV 13, 2014

VIN (Vehicle Identification Number) Range

Begin : 4VZVV1E92FC078029

End : 4VZVU1E97FC079583

 Not sequential VINs**Description of Defect :**

Description of the Defect : On 2015 Newmar Essex Class A motorhomes, the steering column may have inadequate spline engagement at the steering gear. This could lead to wear and potentially result in the steering shaft becoming disconnected or slipping, causing a loss of steering control and increase the risk of a crash causing injury and/or damage to property.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If there is inadequate spline engagement at the steering gear, this could lead to wear and potentially result in the steering shaft

Description of the Cause : The steering slip shaft, between the steering column and steering gear, may have less than specified engagement of the slip shaft. This may cause premature wear of the slip shaft.

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : Spartan Motors Inc.

Address : 1541 Reynolds Road
Charlotte MICHIGAN 48813

Country : United States

Chronology :

1/06/2015 Newmar Corporation received notification of a potential equipment defect relating to motor vehicle safety that may exist in specific steering slip shafts identified as potentially defective by Spartan Motors Inc.

Description of Remedy :

Description of Remedy Program : Spartan will notify owners, dealers will replace the affected slip shaft, free of charge

How Remedy Component Differs from Recalled Component : The new slip shafts will have the minimum specified engagement.

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported