

Part 573 Safety Recall Report**15V-065****Manufacturer Name :** Morgan Olson Corporation**Submission Date :** JUL 21,2015**NHTSA Recall No. :** 15V-065**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Morgan Olson Corporation

Address : 1801 S. Nottawa Street

Strugis MI 49091

Company phone : 616-659-0200

Population :

Number of potentially involved : 11

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2014-2014 Morgan Olson Service Body

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : Service trucks with canopies built on Sprinter cab chassis

Production Dates : APR 11, 2014 - DEC 18, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Noncompliance :**

Description of the Noncompliance : The rear identification lamps are mounted below the doors, despite ample room above the door.

The license plate lamp is mounted incorrectly, causing inconsistent illumination across the plate.

FMVSS 1 : 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS 2 : NR

Description of the Safety Risk : Required lighting on the rear of the truck may not comply with requirements in FMVSS 108

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : United States

Chronology :

An engineering review after transferring production from South Carolina to Michigan indicated issues with the locations of some of the lamps on the rear of the vehicle. After discussions with the body supplier and the lamp manufacturer, we've decided that the lamps as mounted are non-compliant.

Description of Remedy :

Description of Remedy Program : Morgan Olson will modify the existing trucks to add rear identification lights to the portion of the body above the door, and will remount the license plate lamp to a position approved by the lamp manufacturer. In the event that any vehicles have already been modified by the customer, Morgan Olson will request an invoice from them for reimbursement.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Letters sent to dealers and owners on 7-10.

Planned Dealer Notification Date : JUL 21, 2015 - JUL 21, 2015

Planned Owner Notification Date : JUL 21, 2015 - JUL 21, 2015

* NR - Not Reported