

Part 573 Safety Recall Report**15V-095****Manufacturer Name :** Bombardier Recreational Products Inc.**Submission Date :** FEB 13,2015**NHTSA Recall No. :** 15V-095**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Bombardier Recreational Products Inc

Address : 726 Saint-Joseph Street

Valcourt, Quebec - Canada 00 JOE 2LO

Company phone : 450-532-2211

Population :

Number of potentially involved : 5,165

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2013-2013 Can-Am Spyder RT

Vehicle Type : MOTORCYCLES

Body Style : OTHER

Power Train : GAS

Descriptive Information : Can-Am Spyder RT Roadsters, model year 2013.

Production Dates : JAN 23, 2013 - JUN 26, 2013

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Under very hot ambient conditions and low speed riding, the temperature in the engine compartment may rise and thereby increase the risk of a skin burn or a vehicle fire.

Description of the Safety Risk : Increase the risk of a skin burn or a vehicle fire.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

FOREIGN STATES

Country : NR

Chronology :

During the course of the investigation opened by the National Highway Transportation and Safety Administration (NHTSA) in the United States, PE-025, tests were performed by BRP in the end of January 2015. Following those tests and after discussions with NHTSA in February 2015, BRP decided to proceed with a safety recall on all RT models 2013 worldwide.

Description of Remedy :

Description of Remedy Program : BRP is currently preparing to launch a voluntary safety campaign to remedy the condition.

BRP will notify each registered owner of an involved vehicle with an interim safety recall letter and later with another letter when the remedy will be available.

All of this will be performed at no charge.

BRP will also notify its dealers of the campaign. In addition, BRP will post an interim letter to dealer's attention on its dealer website and when the remedy is available, will post the safety campaign bulletin. Information about the campaign will also be posted on BRP Can-Am public website.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : BRP will launch this recall during the week of February 16, 2015 including the interim notification to owners. A second letter will be sent when the remedy is available.

The solution is under validation. BRP is planning its availability starting in May 2015.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported