

Part 573 Safety Recall Report**15V-105****Manufacturer Name :** Daimler Trucks North America LLC**Submission Date :** FEB 18,2015**NHTSA Recall No. :** 15V-105**Manufacturer Recall No. :** FL-678**Manufacturer Information :**

Manufacturer Name : Daimler Trucks North America LLC

Address : 4747 N. Channel Avenue

Portland OR 97217-3849

Company phone : 800-745-8000

Population :

Number of potentially involved : 14

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2014-2015 Freightliner Cascadia

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Vehicles identified by Agility Fuel Systems as part of NHTSA recall 14E-056.

Production Dates : NOV 19, 2013 -JUL 14, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Please see Agility Fuel Systems recall 14E-056 that states "The stainless steel braid reinforcement on some of the Motion Industries T1700-06 flexible fuel hoses used in these fuel system applications may be susceptible to premature corrosion near the fitting crimp inside the slave tank enclosure, possibly due to a combination of the accumulation of road salt and the humid environment within the enclosure."

Description of the Safety Risk : Please see Agility Fuel Systems recall 14E-056 that states "If the corrosion progresses and remains undetected, the hose may leak in sufficient volumes as to create a risk of fire if an ignition source is present."

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

FOREIGN STATES

Country : NR

Chronology :

October 2014- Agility Fuel Systems notified DTNA of a potential recall affecting DTNA vehicles.

November 2014- DTNA investigation concluded that DTNA had not manufactured vehicles with the suspect components.

February 2015- Agility Fuel Systems informed DTNA that certain vehicles may have had fuel systems installed by Agility with suspect components.

February 2015- DTNA voluntary decided to conduct a safety campaign to recall affected vehicles.

Description of Remedy :

Description of Remedy Program : The affected vehicles will have the defective hose replaced. Repairs will be performed by Agility Fuel System . Copies of the reimbursement plan will be submitted as a supplemental report when available.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Customer notification will be made by first class mail using Daimler Trucks North America records to determine the customers affected.

Planned Dealer Notification Date : APR 18, 2015 - APR 18, 2015

Planned Owner Notification Date : APR 18, 2015 - APR 18, 2015

* NR - Not Reported