

Part 573 Safety Recall Report**15V-116****Manufacturer Name :** Nissan North America, Inc.**Submission Date :** FEB 24,2015**NHTSA Recall No. :** 15V-116**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Nissan North America, Inc.

Address : P. O. BOX 685001

Franklin TN 37068-5009

Company phone : (999) 999-9999

Population :

Number of potentially involved : 625,000

Estimated percentage with defect : 0

Vehicle Information :

Vehicle : 2013-2015 Nissan Altima

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : Nissan is continuing to investigate which vehicles are involved. However, based on the information gathered so far, this issue appears to affect certain additional MY2013-MY2015 Nissan Altima sedan vehicles manufactured after February 28, 2013 (the date range subject to Recall Number 14V-565). Nissan tentatively concludes that vehicles manufactured after December 31, 2014 are not affected. Nissan will supplement the manufacturing range when it is finalized.

Approximately 625,000 Nissan Altima vehicles manufactured from March 1, 2013 to December 31, 2014 are affected. Nissan is continuing to investigate the number of vehicles involved and will update the affected population when final numbers are available.

Production Dates : MAR 01, 2013 - DEC 31, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Nissan is continuing to investigate the root cause of this issue. However, in the course of field monitoring, Nissan observed a number of incidents outside the Recall 14V-565 population range.

Once Nissan concludes its investigation, we may revise the defect description.

Description of the Safety Risk : If the primary hood latch is released and the vehicle is driven with only the

secondary latch engaged, the secondary hood latch may not hold the hood closed as designed while the vehicle is in motion.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

FOREIGN STATES

Country : NR

Chronology :

Nissan will provide a chronology when it is available.

Description of Remedy :

Description of Remedy Program : Nissan has not finalized the corrective action. We will provide information about the remedy plan when it is finalized. Nissan will implement an interim procedure to inspect and lubricate the secondary hood latch assembly on all subject vehicles manufactured prior to December 31, 2014 in dealer inventory prior to retail sale.

We will not include a statement in the Part 577 owner notification concerning reimbursement for the cost of obtaining a pre-notification remedy as the subject vehicles are under warranty.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Nissan plans to notify dealers on February 27, 2015. If a permanent remedy is not available, Nissan will begin issuing interim owner notifications within 60 days.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported