

**Part 573 Safety Recall Report****15V-263****Manufacturer Name :** Starcraft Bus**Submission Date :** MAY 04,2015**NHTSA Recall No. :** 15V-263**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Starcraft Bus

Address : 2367 Century Drive  
Goshen IN 46528

Company phone : 800-348-7440

**Population :**

Number of potentially involved : 20

Estimated percentage with defect : 100

**Vehicle Information :**

Vehicle : 2015-2015 Ford and General Motors Prodigy and Quest

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : School Bus Seat Bottom Assemblies W/ Virgin Foam Core may have been  
manufactured integrating foam that does not meet the requirements of FMVSS 302.

Production Dates : AUG 21, 2014 - APR 16, 2015

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**Description of the Defect : HSM has determined that certain School Bus Seat Bottom Assemblies W/ Virgin  
Foam Core may have been manufactured integrating foam that does not meet the  
requirements of FMVSS 302. The non-compliant foam was only utilized in certain  
seat bottom assemblies, all other components within the school bus seat are not  
affected by this recall.Description of the Safety Risk : Seat cushions that do not meet flammability standards will, in the event of a  
fire, burn at a more accelerated rate than materials that do meet the  
flammability standard of FMVSS 302.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

**Supplier Identification :****Component Manufacturer**

Name : HSM Inc

Address : 417 N. Kibler St.

New Washington OHIO 44854

Country : United States

**Chronology :**

NR

**Description of Remedy :**

Description of Remedy Program : HSM has agreed to remedy the vehicles effected by the recall. The seat bottom assembly must be removed, and then replaced with a new seat bottom assembly as supplied by HSM. Seat bottom replacement must be conducted in accordance with the enclosed Work Instructions INS-078 and INS-079. HSM has manufactured new seat bottom assemblies utilizing a foam core that meets the requirements of C/FMVSS 302. a parts kit, HSM will provide replacement Seat Bottom Assemblies upon receipt of the Parts Kit Order Card. The expected out of service time necessary to affect repair is .05 hours per seat bottom assembly, plus .25 hours per vehicle to accommodate staging and preparation. HSM will facilitate repairs relating to this recall, including both parts and labor, at no cost to you the manufacturer or to the vehicle owner. Repair parts for this recall are anticipated to be available for shipment on or before 04/20/2015.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : MAY 11, 2015 - MAY 15, 2015

Planned Owner Notification Date : MAY 11, 2015 - MAY 15, 2015

\* NR - Not Reported