OMB Control No.: 2127-0004

Part 573 Safety Recall Report

15V-286

Manufacturer Name: Toyota Motor Engineering & Manufacturing

Submission Date: NOV 09, 2017 NHTSA Recall No.: 15V-286

Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: Toyota Motor Engineering &

Manufacturing

Address: 6565 Headquarters Drive

Plano TX 75024

Company phone: 1-800-331-4331

Population:

Number of potentially involved: 1,069,055 Estimated percentage with defect:

Vehicle Information:

Vehicle 1: 2002-2007 Lexus SC

Vehicle Type: **Body Style:** Power Train: NR

Descriptive Information: (1) The above referenced vehicles include those covered by previous recall 14V-655

and the additional population reported here.

(2) Although the involved vehicles are within the above VIN range, not all vehicles in

this range were sold in the U.S.

Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. As noted in the May Amendment to the Coordinated Remedy Order, the length of time that a non-desiccated frontal Takata PSAN inflator will have reached the point where they pose an unreasonable risk to safety could be quite long and is dependent on the age of the inflator and environmental exposure, among other factors.

[July 17, 2017] – Toyota submitted its notice to utilize provisions and requirements of Paragraph 45 and the "other" reporting category pursuant to Paragraphs 46-47 of the December 9, 2016 ACRO. Counts of these vehicles are indicated in the attached supplement and are current as of June 20, 2017.

Production Dates: JAN 08, 2001 - AUG 03, 2007

VIN Range 1: Begin: Not sequential End: NR

Vehicle 2: 2003-2007 Toyota Corolla Matrix

Vehicle Type: **Body Style:** Power Train: NR

Descriptive Information: (1) The above referenced vehicles include those covered by previous recall 14V-655

and the additional population reported here.

(2) Although the involved vehicles are within the above VIN range, not all vehicles in

The information contained in this report was submitted pursuant to 49 CFR §573

	this range were	sold in the U.S.						
	Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. As noted in the May Amendment to the Coordinated Remedy Order, the length of time that a non-desiccated frontal Takata PSAN inflator will have reached the point where they pose an unreasonable risk to safety could be quite long and is dependent on the age of the inflator and environmental exposure, among other factors.							
	[July 17, 2017] – Toyota submitted its notice to utilize provisions and requirements of Paragraph 45 and the "other" reporting category pursuant to Paragraphs 46-47 of the December 9, 2016 ACRO. Counts of these vehicles are indicated in the attached supplement and are current as of June 20, 2017.							
Production Dates : VIN Range 1 :		UN 05, 2007 NR	End:	NR		Not sequential		
	8							
Vehicle Type : Body Style :		ota Corolla						
Power Train :	: NR							
Descriptive Information :	 (1) The above referenced vehicles include those covered by previous recall 14V-655 and the additional population reported here. (2) Although the involved vehicles are within the above VIN range, not all vehicles in this range were sold in the U.S. 							
	Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. As noted in the May Amendment to the Coordinated Remedy Order, the length of time that a non-desiccated frontal Takata PSAN inflator will have reached the point where they pose an unreasonable risk to safety could be quite long and is dependent on the age of the inflator and environmental exposure, among other factors.							
	[July 17, 2017] – Toyota submitted its notice to utilize provisions and requirements of Paragraph 45 and the "other" reporting category pursuant to Paragraphs 46-47 of the December 9, 2016 ACRO. Counts of these vehicles are indicated in the attached supplement and are current as of June 20, 2017.							
Production Dates :								
VIN Range 1:	: Begin :	NR	End:	NR		☐ Not sequential		
Vehicle 4 : Vehicle Type :	: 2003-2006 Toy	ota Tundra						
Body Style :								
Power Train								
Descriptive Information	: (1) The above r and the additio	nal population i e involved vehi	eported	here.	0.1	ous recall 14V-655 e, not all vehicles in		

Production Dates : VIN Range 1 :	contain the defe Order, the lengt reached the point and is dependent factors. [July 17, 2017] - Paragraph 45 and December 9, 20 supplement and JUL 30, 2002 - D	ct. As noted in the first of time that a not where they put on the age of the Toyota submited the "other" real of ACRO. Count hare current as	he May a non-des ose an u the infla- tted its n eporting s of thes	Amendment to the iccated frontal Tanreasonable risk tor and environn otice to utilize procategory pursuate vehicles are incept, 2017.	ge of vehicles to actually the Coordinated Remedy akata PSAN inflator will have to safety could be quite long mental exposure, among other rovisions and requirements of the Paragraphs 46-47 of the dicated in the attached			
Vahiala E.	2003-2007 Pon	ria a Viba						
Vehicle Type :	2003-2007 POII	nac vide						
Body Style :								
Power Train :	NR							
Descriptive Information :	(1) The above re	eferenced vehic	les inclu	de those covered	by previous recall 14V-655			
	and the additional population reported here. (2) Although the involved vehicles are within the above VIN range, not all vehicles in							
	(2) Although the this range were		cles are v	vithin the above	VIN range, not all vehicles in			
	tins range were	sold in the c.s.						
	Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. As noted in the May Amendment to the Coordinated Remedy Order, the length of time that a non-desiccated frontal Takata PSAN inflator will have reached the point where they pose an unreasonable risk to safety could be quite long and is dependent on the age of the inflator and environmental exposure, among other factors.							
	[October 19, 2017] - General Motors informed Toyota that it has notified the Agency regarding its intent to utilize the provisions and requirements of Paragraph 45 and							
					6-47 of the December 9, 2016			
Production Dates :	JAN 18. 2002 - J	UN 04, 2007						
VIN Range 1:		NR	End:	NR	☐ Not sequential			
Vahiala C.	2002 2007 Tass	oto Cognojo						
Vehicle Type :	2002-2007 Toy	ota Sequoia						
Body Style :								
Power Train :	NR							
Descriptive Information :		eferenced vehic	les inclu	de those covered	by previous recall 14V-655			
1	and the addition	al population r	eported	here.	v -			
	(2) Although the	e involved vehic	les are v	vithin the above	VIN range, not all vehicles in			

this range were sold in the U.S.

Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. As noted in the May Amendment to the Coordinated Remedy Order, the length of time that a non-desiccated frontal Takata PSAN inflator will have reached the point where they pose an unreasonable risk to safety could be quite long and is dependent on the age of the inflator and environmental exposure, among other factors.

[July 17, 2017] – Toyota submitted its notice to utilize provisions and requirements of Paragraph 45 and the "other" reporting category pursuant to Paragraphs 46-47 of the December 9, 2016 ACRO. Counts of these vehicles are indicated in the attached supplement and are current as of June 20, 2017.

Production Dates: APR 02, 2002 - NOV 08, 2007

VIN Range 1: Begin: NR End: NR Not sequential

Description of Defect:

Description of the Defect: This is an amendment to Recall 15V-286, the prioritized population of vehicles in areas of High Absolute Humidity (HAH), in light of the Consent Order entered into on May 18, 2015 between the National Highway Traffic Safety Administration ("NHTSA") and Takata, and Part 573 Reports filed by Takata on that date (15E-041, 15E-042, and 15E-043). The subject vehicles are equipped with front passenger air bag inflators (Takata-designated SPI, PSPI, or PSPI-L) which, according to the Part 573 Reports submitted by Takata, may have been manufactured in such a way as to have a potential for the intrusion of moisture over time. Depending on the circumstances, this potential condition could create excessive internal pressure when the air bag is deployed, which could result in the body of the inflator rupturing upon deployment. In the event of an inflator rupture, metal fragments could pass through the air bag cushion material, which may result in injury or death to vehicle occupants.

> FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Depending on the circumstances, this potential condition could create

excessive internal pressure when the air bag is deployed, which could result in the body of the inflator rupturing upon deployment. In the event of an inflator rupture, metal fragments could pass through the air bag cushion

material, which may result in injury or death to vehicle occupants.

Description of the Cause: NR Identification of Any Warning NR that can Occur:

Supplier Identification:

Component Manufacturer

Name: TK Holdings Inc. Address: 2500 Takata Drive

Auburn Hills MICHIGAN 48326

Country: United States

Chronology:

Please see the attached amended Part 573 report that was submitted on June 16, 2015 for the chronology.

Description of Remedy:

Description of Remedy Program: All known owners of the affected Toyota and Lexus vehicles will be

notified by first class mail to return their vehicles to a Toyota or Lexus dealer, as applicable. The dealer will replace the front passenger airbag inflator with a newly manufactured one. The owner letter will instruct vehicle owners who have paid to have this condition remedied prior to this campaign to seek reimbursement pursuant to Toyota's General Reimbursement Plan. General Motors will notify NHTSA separately of its repair and notification schedule. Pursuant to 577.11(e), General Motors will provide reimbursement to owners for repairs completed on or before ten days after GM mails owner letters, pursuant to the plan submitted on May 20, 2015. In addition, please see section 8 in the attached amended Part 573 report that was submitted on June 16, 2015.

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: Notifications to distributors/dealers were sent on June 15, 2015. Copies

of dealer communications will be submitted as they are issued. Please also see section 8 in the attached amended Part 573 report that was

submitted on June 16, 2015.

Planned Dealer Notification Date : NR - NR Planned Owner Notification Date : NR - NR

* NR - Not Reported