

Part 573 Safety Recall Report**15V-287****Manufacturer Name :** Nissan North America, Inc.**Submission Date :** NOV 06,2015**NHTSA Recall No. :** 15V-287**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Nissan North America, Inc.

Address : P. O. BOX 685001

Franklin TN 37068-5009

Company phone : 800-647-7261

Population :

Number of potentially involved : 1,090,569

Estimated percentage with defect : 0

Vehicle Information :

Vehicle : 2002-2004 Nissan Pathfinder

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : GAS

Descriptive Information : The vehicles subject to this report include all Nissan vehicles equipped with SPI front passenger air bags (PAB) inflators, including those previously recalled under 13V-136, 14V-361, 14V-701, and 15V-226.

Further, Recall 15V-287 will also include certain vehicles equipped with PSPI PAB inflators previously subject to national recalls 13V-136 and 14V-361.

Production Dates : JUL 16, 2001 - JUL 19, 2004

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2002-2006 Nissan Sentra

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : The vehicles subject to this report include all Nissan vehicles equipped with SPI front passenger air bags (PAB) inflators, including those previously recalled under 13V-136, 14V-361, 14V-701, and 15V-226.

Further, Recall 15V-287 will also include certain vehicles equipped with PSPI PAB inflators previously subject to national recalls 13V-136 and 14V-361.

Production Dates : JUL 30, 2001 - AUG 26, 2006

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2001-2003 Nissan Maxima

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : The vehicles subject to this report include all Nissan vehicles equipped with SPI front passenger air bags (PAB) inflators, including those previously recalled under 13V-136, 14V-361, 14V-701, and 15V-226.

Further, Recall 15V-287 will also include certain vehicles equipped with PSPI PAB inflators previously subject to national recalls 13V-136 and 14V-361.

Production Dates : JUN 20, 2000 - DEC 16, 2002

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2001-2001 Infiniti I30

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : The vehicles subject to this report include all Nissan vehicles equipped with SPI front passenger air bags (PAB) inflators, including those previously recalled under 13V-136, 14V-361, 14V-701, and 15V-226.

Further, Recall 15V-287 will also include certain vehicles equipped with PSPI PAB inflators previously subject to national recalls 13V-136 and 14V-361.

Production Dates : JUN 02, 2000 - AUG 04, 2001

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2002-2003 Infiniti I35

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : The vehicles subject to this report include all Nissan vehicles equipped with SPI front passenger air bags (PAB) inflators, including those previously recalled under 13V-136, 14V-361, 14V-701, and 15V-226.

Further, Recall 15V-287 will also include certain vehicles equipped with PSPI PAB inflators previously subject to national recalls 13V-136 and 14V-361.

Production Dates : JUL 10, 2001 - JUN 03, 2003

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2002-2003 Infiniti QX4

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : The vehicles subject to this report include all Nissan vehicles equipped with SPI front passenger air bags (PAB) inflators, including those previously recalled under 13V-136, 14V-361, 14V-701, and 15V-226.

Further, Recall 15V-287 will also include certain vehicles equipped with PSPI PAB inflators previously subject to national recalls 13V-136 and 14V-361.

Production Dates : JUL 16, 2001 - OCT 31, 2002

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2003-2005 Infiniti FX35/FX45

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : GAS

Descriptive Information : The vehicles subject to this report include all Nissan vehicles equipped with SPI front passenger air bags (PAB) inflators, including those previously recalled under 13V-136, 14V-361, 14V-701, and 15V-226.

Further, Recall 15V-287 will also include certain vehicles equipped with PSPI PAB inflators previously subject to national recalls 13V-136 and 14V-361.

Production Dates : NOV 21, 2002 - JUN 15, 2003

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : This information will be supplemented on November 9, 2015.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : This inflator could be susceptible to moisture intrusion, possibly resulting in abnormal passenger air bag deployment in the event of a crash, increasing the risk of injury to the occupant.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : TK HOLDINGS INC.

Address : 2500 Takata Drive
Auburn Hills MICHIGAN 48326

Country : United States

Chronology :

This information will be supplemented on November 9, 2015.

Description of Remedy :

Description of Remedy Program : Nissan will notify vehicle owners by first class mail. Owner notification will be completed within 60 days. The front passenger air bag inflator will be replaced with a new one at no cost to owners for parts or labor. Nissan anticipates having enough replacement parts on hand and will address any potential short-term service issues with individual customers on case-by-case basis.

We will include a statement in the Part 577 owner notification concerning reimbursement for the cost of obtaining a pre-notification remedy.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Nissan will notify vehicle owners by first class mail. Owner notification will be completed within 60 days.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported