

Part 573 Safety Recall Report**15V-299****Manufacturer Name :** Forest River, Inc.**Submission Date :** MAY 15,2015**NHTSA Recall No. :** 15V-299**Manufacturer Recall No. :** 17B-05132015-0036**Manufacturer Information :**

Manufacturer Name : Forest River, Inc.

Address : 55470 CR 1

P.O. Box 3030 Elkhart IN 46515-3030

Company phone : 219-533-5934

Population :

Number of potentially involved : 205

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2015-2016 Vengeance VGF377V, VGF378V, VGF394V13 and VGF396V

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : Vengeance Fifth Wheel Toy Hauler Recreational Vehicle

Production Dates : AUG 07, 2014 - MAY 12, 2015

VIN (Vehicle Identification Number) Range

Begin : 4X4FVGH21FY206815

End : 4X4FVGS3XEY206022

☒ Not sequential VINs**Description of Noncompliance :**

Description of the Noncompliance : GVWR on labels indicates 18,500 pounds. The GVWR on the labels should be 18,000 pounds

FMVSS 1 : 567 - Certification

FMVSS 2 : NR

Description of the Safety Risk : The unit can be loaded so that the GVWR exceeds the labeled GVWR of the hitch head pin box.

Description of the Cause : There was a typographical error when the GVWR was entered into the computer system that creates the labels when the unit is weighed.

Identification of Any Warning that can Occur : It is unlikely that there will be any indication of overload. These units all have 3-6,000 pound axles and ST235/80R16 LRE tires @80 PSI.

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

The warranty/Service department of the division manufacturing these units received a call from a dealer on 5/13/2015 stating that the GVWR label on the hitch head pin box was less than the GVWR on the Federal Certification label, in reviewing the information in the computer system it was discovered that 4 of the Vengeance toy haulers had the incorrect GVWR. The computer system was changed immediately, all units that had been labeled but were to be shipped are on hold until new correct labels can be run and applied.

Description of Remedy :

Description of Remedy Program : We will send the corrected labels to all retail customers and dealers of record. There will be no cost to remove the incorrect labels and put on the correct labels to the retail customers and all dealers will be reimbursed for their time under our warranty program.

How Remedy Component Differs from Recalled Component : There will not be any distinguishable difference in the recall replacement labels or the new production labels.

Identify How/When Recall Condition was Corrected in Production : the computer system was corrected immediately, all units that have not been shipped to dealers are on hold and will have corrected labels applied before they are shipped.

Recall Schedule :

Description of Recall Schedule : The dealer and retail letters will be sent as soon as we obtain a recall number and the corrected labels are printed off.

Planned Dealer Notification Date : MAY 22, 2015 - MAY 22, 2015

Planned Owner Notification Date : MAY 29, 2015 - MAY 29, 2015

* NR - Not Reported