

Part 573 Safety Recall Report**15V-307****Manufacturer Name :** Collins Bus Corporation**Submission Date :** MAY 15,2015**NHTSA Recall No. :** 15V-307**Manufacturer Recall No. :** 15E032**Manufacturer Information :**

Manufacturer Name : Collins Bus Corporation

Address : P.O. Box 2946

Hutchinson KS 67504

Company phone : 9999

Population :

Number of potentially involved : 13

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2015-2015 Collins DE516WR,SL408,SH40,DH500

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : Collins buses equipped with HSM seat bottoms ranging from 26" to 45" wide.

Products affected by this recall were manufactured by HSM with shipping dates between February 2, 2015 and April 01 2015. Collins Bus Corporation decided that this defect existed in these vehicles on April 15, 2015.

Production Dates : FEB 02, 2015 - APR 01, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : On April 15 2015 Collins Bus was notified by HSM that certain school bus seat assemblies may contain a foam core that does not meet the requirements of FMVSS 302. This Non-Compliant foam was only utilized in certain seat bottom assemblies, all other components within the school bus seat are not affected by this recall.

Description of the Safety Risk : The foam does not meet FMVSS302

Description of the Cause : NR

Identification of Any Warning that can Occur : There is no visual or audible warning which would define this condition. All seat bottom assemblies indicated in this notice are presumed to contain the defect and must be repaired in accordance with the enclosed work instructions INS-079.

Supplier Identification :**Component Manufacturer**

Name : HSM Transportation Solutions

Address : 2601 Northland Drive

Elkhart INDIANA 46514

Country : United States

Chronology :

On April 15 2015 Collins Bus was notified by HSM that certain school bus seat assemblies may contain a foam core that does not meet the requirements of FMVSS 302. This Non-Compliant foam was only utilized in certain seat bottom assemblies, all other components within the school bus seat are not affected by this recall.

Previously manufactured units did not contain the affected HSM seat cushion. Subsequently manufactured units do not contain the defect.

Description of Remedy :

Description of Remedy Program : To correct this condition, the seat bottom assembly must be removed, and then replaced with a new seat bottom assembly as supplied by HSM. Seat bottom replacement must be conducted in accordance with the enclosed Work Instructions INS-079. HSM has manufactured new seat bottom assemblies utilizing a foam core that meets the requirements of FMVSS 302. a parts kit, HSM will provide replacement Seat Bottom Assemblies upon receipt of the Parts Kit Order Card. The expected out of service time necessary to affect repair is .05 hours per seat bottom assembly, plus .25 hours per vehicle to accommodate staging and preparation. HSM will facilitate repairs relating to this recall, including both parts and labor, at no cost to the vehicle owner. Repair parts for this recall are anticipated to be available for shipment on or before 04/20/2015.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : As of April 1, 2015 HSM had production remedies in place to prevent these defects.

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : MAY 22, 2015 - MAY 25, 2015

Planned Owner Notification Date : MAY 27, 2015 - MAY 29, 2015

* NR - Not Reported