The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety	Recall Report
-----------------	---------------

Manufacturer Name : Chrysler (FCA US LLC) Submission Date : MAR 22, 2016 NHTSA Recall No. : 15V-313 Manufacturer Recall No. : R25

Manufacturer Name : Chrysler (FCA US LLC)

Manufacturer Information :

Address : 800 Chrysler Drive

CIMS 482-00-91 Aut	ourn Hills MI 48326-2757	
Company phone : 1-800-853-1	403	
Vehicle Information :		
Vehicle: 2008-2010 Dodge R	am 4500/5500 Cab Chassis	
Vehicle Type :		
Body Style :		
Power Train : NR		
driv	"DM" vehicles being recalled are those equer airbag inflators.	quipped with Takata "PSDI-4" front
Production Dates : JAN 01, 20	J7 - DEC 31, 2010	
VIN (Vehicle Identification 1	Number) Range	
Begin : NR	End : NR	☐ Not sequential VINs
Vehicle:2005-2009 Dodge R	am 1500, 2500, 3500 Pickup	
Vehicle Type :		
Body Style :		
Power Train : NR		
1	"DH" vehicles being recalled are those eq er airbag inflators.	uipped with Takata "PSDI-4" front
Production Dates : JAN 01, 20	04 - DEC 31, 2009	
VIN (Vehicle Identification 1	Number) Range	
Begin : NR	End : NR	Not sequential VINs
Vehicle: 2004-2008 Dodge R	am 1500, 2500, 3500 Pickup	
Vehicle Type :	1	
Body Style :		
Power Train : NR		



Number of potentially involved : 4,054,473

Estimated percentage with defect : 1

15V-313

Population :

t 573 Safety Recall Rep	ort	15V-313	Pag
-	DR" vehicles being recalled are those r airbag inflators. 3 - DEC 31, 2008	equipped with Takata "PSD	I-4" front
VIN (Vehicle Identification N	umber) Range		
Begin : NR	End : NR	Not see	quential VINs
-	D1" vehicles being recalled are those r airbag inflators.	equipped with Takata "PSD	I-4" front
VIN (Vehicle Identification N	umber) Range		
Begin : NR	End : NR	Not see	quential VINs
-	DC" vehicles being recalled are those r airbag inflators. 6 - DEC 31, 2009	equipped with Takata "PSD	I-4" front
VIN (Vehicle Identification N	umber) Range		
Begin : NR	End : NR	Not see	quential VINs
1	HB" vehicles being recalled are those r airbag inflators.	equipped with Takata "PSD	I-4" front
VIN (Vehicle Identification N	umber) Range		
Begin : NR	End : NR	Not see	quential VINs
Vehicle : 2006-2009 Mitsubish Vehicle Type : Body Style : Power Train : NR	i Raider		

The information contained in this report was submitted pursuant to 49 CFR §5/3

rt 573 Safety Recall Rep	ort	15V-313	Pag
	NM" vehicles being recalled are those r airbag inflators. 5 - DEC 31, 2009	equipped with Takata "PSDI	-4" front
VIN (Vehicle Identification N	umber) Range		
Begin : NR	End : NR	🗌 Not seq	uential VINs
-	HG" vehicles being recalled are those rairbag inflators.	equipped with Takata "PSDI	-4" front
VIN (Vehicle Identification N	umber) Range		
Begin : NR	End : NR	Not seq	uential VINs
-	LX" vehicles being recalled are those e r airbag inflators. 4 - DEC 31, 2010	equipped with Takata "PSDI-	4" front
VIN (Vehicle Identification N	umber) Range		
Begin : NR	End : NR	🗌 Not seq	uential VINs
	LX" vehicles being recalled are those or airbag inflators.	equipped with Takata "PSDI-	4" front
VIN (Vehicle Identification N	umber) Range		
Begin : NR	End : NR	🗌 Not seq	uential VINs
Vehicle: 2005-2011 Dodge Da Vehicle Type: Body Style:	kota		

rt 573 Safety Recall Report		15V-313	Рад
Descriptive Information : The "ND" v driver airba Production Dates : JAN 01, 2004 - DE	ag inflators.	quipped with Takata "I	PSDI-4" front
VIN (Vehicle Identification Numbe			
Begin : NR	End : NR		t sequential VINs
Vehicle : 2005-2008 Dodge Magnum Vehicle Type : Body Style : Power Train : NR Descriptive Information : The "LX" ve driver airba Production Dates : JAN 01, 2004 - DE	chicles being recalled are those eq ag inflators. C 31, 2008	juipped with Takata "F	'SDI-4" front
VIN (Vehicle Identification Numbe Begin : NR	r) Range End : NR		t sequential VINs
arise in som	kata has determined that a defect e of the subject inflators. The bat	related to motor vehic wing-shaped propella	cle safety may nt wafers in
potentially l deployment excessive in	subject inflators may experience ead to over-aggressive combustic . Depending on the circumstances ternal pressure when the air bag	on in the event of an air s, this potential conditi is deployed, which cou	r bag on could create
FMVSS 1 :NR FMVSS 2 :NR	inflator rupturing upon deployme	ent.	
Description of the Safety Risk : Per Tak the even cushion	nt of an inflator rupture, metal fra material, which may result in inj	agments could pass thr ury or death to vehicle	ough the air bag occupants."
subject infla	n to date, the potential for such r tors after several years of exposu	uptures may occur in s	ome of the
absolute hur dentification of Any Warning that can			

The information contained in this report was submitted pursuant to 49 CFR \$573

Supplier Identification :

Component Manufacturer Name : Takata Corporation Address : 2500 Takata Drive Auburn Hills MICHIGAN 48326 Country : United States

Chronology:

Please see attached supplemental information titled "FCA US LLC Chronology (15V-313) Takata PSDI-4 061015".

Description of Remedy :

Description of Remedy Program : FCA US LLC ("FCA US") will conduct a voluntary safety recall on all affected vehicles to replace the front driver airbag inflator.

FCA US has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, FCA US, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the company for confirmation of the expense.

How Remedy Component Differs from Recalled Component : At this time, the remedy component has yet to be determined.

Identify How/When Recall Condition was Corrected in Production : NR

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

15V-313

Recall Schedule :	
Description of Recall Schedule	: **2016 03 22 - Target Phase 5 Owner notification - 3/31/2016
	2/25/2016 Update: Stage 4: Final Owner Notification Begin Date: March 10, 2016.
	**(Stage 4)Final Owner Notification Begin Date: Evaluate Part Supply Status in 4th Qtr 2016
	**(Stage 5) Final Owner Notification Begin Date: Evaluate Part Supply Status in 1st Qtr 2017
	Dealer Notification Begin Date: 6/8/2015
	Dealer Notification End Date: TBD
	Final Owner Notification (Stage 1) Begin Date: 6/8/2015
	Final Owner Notification (Stage 1) End Date: 6/19/2015
	Interim Owner Notification (Stage 2-5) Begin Date: 6/15/2015
	Interim Owner Notification (Stage 2-5) End Date: 7/13/2015
	Final Owner Notification (Stage 2) Begin Date: 8/31/2015
	Final Owner Notification (Stage 2) End Date: 8/31/2015
	Final Owner Notification (Stage 3) Begin Date: 11/30/2015
	Final Owner Notification (Stage 3) End Date: 11/30/2015
	Final Owner Notification (Stage 4) Begin Date: TBD
	Final Owner Notification (Stage 4) End Date: TBD
	Final Owner Notification (Stage 5) Begin Date: TBD
	Final Owner Notification (Stage 5) End Date: TBD
Planned Dealer Notification Da	tte : NR - NR
Planned Owner Notification Da	ate : NR - NR

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573