

Part 573 Safety Recall Report**15V-313****Manufacturer Name :** Chrysler (FCA US LLC)**Submission Date :** MAY 26,2015**NHTSA Recall No. :** 15V-313**Manufacturer Recall No. :** R25**Manufacturer Information :**

Manufacturer Name : Chrysler (FCA US LLC)

Address : 800 Chrysler Drive

CIMS 482-00-91 Auburn Hills MI 48326-2757

Company phone : 1-800-853-1403

Population :

Number of potentially involved : 4,066,732

Estimated percentage with defect : 1

Vehicle Information :

Vehicle : 2005-2009 Dodge Ram 2500 Pickup

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The "DH" vehicles being recalled are those equipped with Takata "PSDI-4" front driver airbag inflators.

Production Dates : JAN 01, 2004 - DEC 31, 2009

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2004-2008 Dodge Ram 1500 Pickup

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The "DR" vehicles being recalled are those equipped with Takata "PSDI-4" front driver airbag inflators.

Production Dates : JAN 01, 2003 - DEC 31, 2008

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2006-2009 Dodge Ram 3500 Pickup

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The "D1" vehicles being recalled are those equipped with Takata "PSDI-4" front driver airbag inflators.

Production Dates : JAN 01, 2005 - DEC 31, 2009

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Vehicle : 2007-2009 Dodge Ram 3500 Cab Chassis

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The "DC" vehicles being recalled are those equipped with Takata "PSDI-4" front driver airbag inflators.

Production Dates : JAN 01, 2006 - DEC 31, 2009

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Vehicle : 2008-2010 Dodge Ram 4500/5500 Cab Chassis

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The "DM" vehicles being recalled are those equipped with Takata "PSDI-4" front driver airbag inflators.

Production Dates : JAN 01, 2007 - DEC 31, 2010

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Vehicle : 2008-2009 Sterling 4500, 5500 Cab Chassis

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The "DA" vehicles being recalled are those equipped with Takata "PSDI-4" front driver airbag inflators.

Production Dates : JAN 01, 2007 - DEC 31, 2009

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Vehicle : 2004-2008 Dodge Durango

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The "HB" vehicles being recalled are those equipped with Takata "PSDI-4" front driver airbag inflators.

Production Dates : JAN 01, 2003 - DEC 31, 2008

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Vehicle : 2007-2008 Chrysler Aspen

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The "HG" vehicles being recalled are those equipped with Takata "PSDI-4" front driver airbag inflators.

Production Dates : JAN 01, 2006 - DEC 31, 2008

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Vehicle : 2005-2010 Chrysler 300, 300C, SRT8

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The "LX" vehicles being recalled are those equipped with Takata "PSDI-4" front driver airbag inflators.

Production Dates : JAN 01, 2004 - DEC 31, 2010

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Vehicle : 2005-2010 Dodge Charger, Magnum

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The "LX" vehicles being recalled are those equipped with Takata "PSDI-4" front driver airbag inflators.

Production Dates : JAN 01, 2004 - DEC 31, 2010

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Vehicle : 2005-2011 Dodge Dakota

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The "ND" vehicles being recalled are those equipped with Takata "PSDI-4" front driver airbag inflators.

Production Dates : JAN 01, 2004 - DEC 31, 2011

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Vehicle : 2006-2010 Mitsubishi Raider

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The "NM" vehicles being recalled are those equipped with Takata "PSDI-4" front driver airbag inflators.

Production Dates : JAN 01, 2005 - DEC 31, 2010

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Description of Defect :

Description of the Defect : On May 18, 2015, Takata submitted a 573 Safety Defect Information Report to NHTSA, "Takata has determined that a defect related to motor vehicle safety may arise in some of the subject inflators. The batwing-shaped propellant wafers in some of the subject inflators may experience an alteration over time, which could potentially lead to over-aggressive combustion in the event of an air bag deployment. Depending on the circumstances, this potential condition could create excessive internal pressure when the air bag is deployed, which could result in the body of the inflator rupturing upon deployment."

Description of the Safety Risk : Per Takata's May 18, 2015 573 Safety Defect Information Report (15E-040), "in the event of an inflator rupture, metal fragments could pass through the air bag cushion material, which may result in injury or death to vehicle occupants."

Description of the Cause : Based upon Takata's May 18, 2015 573 Safety Defect Information Report (15E-040), "investigation to date, the potential for such ruptures may occur in some of the subject inflators after several years of exposure to persistent conditions of high absolute humidity."

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : Takata Corporation

Address : 2500 Takata Drive

Auburn Hills MICHIGAN 48326

Country : United States

Chronology :

Please see attached supplemental information titled "FCA US LLC Chronology (15V-XXX) Takata PSDI-4 052615".

Description of Remedy :

Description of Remedy Program : FCA US LLC ("FCA US") will conduct a voluntary safety recall on all affected vehicles to replace the front driver airbag inflator.

FCA US has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, FCA US, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the company for confirmation of the expense.

How Remedy Component Differs from Recalled Component : At this time, the remedy component has yet to be determined.

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Planned Dealer Notification Begin Date: TBD
Planned Dealer Notification End Date: TBD
Planned Owner Notification Begin Date: TBD
Planned Owner Notification End Date: TBD

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported