



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

15V313

Manufacturer Name: Chrysler (FCA US, LLC)

Submission Date: Jan 29, 2026

NHTSA Recall No.: 15V313

Manufacturer Recall No.: R25

Manufacturer Information

Population

Manufacturer Name: Chrysler (FCA US, LLC)

Address: 800 Chrysler Drive
CIMS 482-00-91
Auburn Hills MI, 48326-
2757

Total number of potentially involved: 4,077,169

Estimated percentage with defect: 1%

Vehicle Information

Vehicle 1: 2006-2009 Mitsubishi Raider

Product Category:

Product Type:

Fuel / Propulsion:

Production Dates: Jan 01, 2005 - Dec 31, 2009

Number of potentially involved:

Descriptive Information:

The "NM" vehicles being recalled are those equipped with Takata "PSDI-4" front driver airbag inflators.

Vehicle 2: 2005-2011 Dodge Dakota

Product Category:

Product Type:

Fuel / Propulsion:

Production Dates: Jan 01, 2004 - Dec 31, 2011

Number of potentially involved:

Descriptive Information:

The "ND" vehicles being recalled are those equipped with Takata "PSDI-4" front driver airbag inflators.

Vehicle 3: 2006-2009 Dodge Ram 3500 Pickup

Product Category:

Part 573 Safety Recall Report**15V313****Product Type:****Fuel / Propulsion:****Production Dates:** Jan 01, 2005 - Dec 31, 2009**Number of potentially involved:****Descriptive Information:**

The "D1" vehicles being recalled are those equipped with Takata "PSDI-4" front driver airbag inflators.

Vehicle 4: 2005-2009 Dodge Ram 1500, 2500, 3500 Pickup**Product Category:****Product Type:****Fuel / Propulsion:****Production Dates:** Jan 01, 2004 - Dec 31, 2009**Number of potentially involved:****Descriptive Information:**

The "DH" vehicles being recalled are those equipped with Takata "PSDI-4" front driver airbag inflators.

Vehicle 5: 2007-2008 Chrysler Aspen**Product Category:****Product Type:****Fuel / Propulsion:****Production Dates:** Jan 01, 2006 - Dec 31, 2008**Number of potentially involved:****Descriptive Information:**

The "HG" vehicles being recalled are those equipped with Takata "PSDI-4" front driver airbag inflators.

Vehicle 6: 2005-2010 Chrysler 300, 300C, 300S, SRT8**Product Category:****Product Type:****Fuel / Propulsion:****Production Dates:** Jan 01, 2004 - Dec 31, 2010**Number of potentially involved:****Descriptive Information:**

Part 573 Safety Recall Report**15V313**

The "LX" vehicles being recalled are those equipped with Takata "PSDI-4" front driver airbag inflators.

Vehicle 7: 2008-2010 Dodge Ram 4500/5500 Cab Chassis

Product Category:

Product Type:

Fuel / Propulsion:

Production Dates: Jan 01, 2007 - Dec 31, 2010

Number of potentially involved:

Descriptive Information:

The "DM" vehicles being recalled are those equipped with Takata "PSDI-4" front driver airbag inflators.

Vehicle 8: 2004-2008 Dodge Durango

Product Category:

Product Type:

Fuel / Propulsion:

Production Dates: Jan 01, 2003 - Dec 31, 2008

Number of potentially involved:

Descriptive Information:

The "HB" vehicles being recalled are those equipped with Takata "PSDI-4" front driver airbag inflators.

Vehicle 9: 2004-2008 Dodge Ram 1500, 2500, 3500 Pickup

Product Category:

Product Type:

Fuel / Propulsion:

Production Dates: Jan 01, 2003 - Dec 31, 2008

Number of potentially involved:

Descriptive Information:

The "DR" vehicles being recalled are those equipped with Takata "PSDI-4" front driver airbag inflators.

Vehicle 10: 2006-2010 Dodge Charger

Product Category:

Product Type:

Fuel / Propulsion:

Part 573 Safety Recall Report

15V313

Production Dates: Jan 01, 2005 - Dec 31, 2010

Number of potentially involved:

Descriptive Information:

The "LX" vehicles being recalled are those equipped with Takata "PSDI-4" front driver airbag inflators.

Vehicle 11: 2007-2009 Dodge Ram 3500 Cab Chassis

Product Category:

Product Type:

Fuel / Propulsion:

Production Dates: Jan 01, 2006 - Dec 31, 2009

Number of potentially involved:

Descriptive Information:

The "DC" vehicles being recalled are those equipped with Takata "PSDI-4" front driver airbag inflators.

Vehicle 12: 2005-2008 Dodge Magnum

Product Category:

Product Type:

Fuel / Propulsion:

Production Dates: Jan 01, 2004 - Dec 31, 2008

Number of potentially involved:

Descriptive Information:

The "LX" vehicles being recalled are those equipped with Takata "PSDI-4" front driver airbag inflators.

Defect / Noncompliance Description

Description of the defect or noncompliance:

On May 18, 2015, Takata submitted a 573 Safety Defect Information Report to NHTSA, "Takata has determined that a defect related to motor vehicle safety may arise in some of the subject inflators. The batwing-shaped propellant wafers in some of the subject inflators may experience an alteration over time, which could potentially lead to over-aggressive combustion in the event of an air bag deployment. Depending on the circumstances, this potential condition could create excessive internal pressure when the air bag is deployed, which could result in the body of the inflator rupturing upon deployment."

FMVSS1:

FMVSS2:

Part 573 Safety Recall Report

15V313**Description of the safety risk, including crash, fire, death, injury:**

Per Takata's May 18, 2015 573 Safety Defect Information Report (15E-040), "in the event of an inflator rupture, metal fragments could pass through the air bag cushion material, which may result in injury or death to vehicle occupants."

Description of the cause:

Based upon Takata's May 18, 2015 573 Safety Defect Information Report (15E-040), "investigation to date, the potential for such ruptures may occur in some of the subject inflators after several years of exposure to persistent conditions of high absolute humidity."

Identification of any warning that can occur:

Component Manufacturer

Tier of Supplier:**Supplier Type:****Name:** Takata Corporation**Address:** 2500 Takata Drive
Auburn Hills MI, 48326**Country:** United States

Involved Components

Component Name 1:**Component Description:****Component Part Number:**

Chronology

Please see attached supplemental information titled "FCA US LLC Chronology (15V-313) Takata PSDI-4 061015".

Related NHTSA Recall Number:

Description of Remedy

Part 573 Safety Recall Report

15V313

Remedy Type: Repair

Consumer Advisories: Do Not Drive Park Outside

Description of remedy program:

FCA US LLC ("FCA US") will conduct a voluntary safety recall on all affected vehicles to replace the front driver airbag inflator.

FCA US has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, FCA US, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the company for confirmation of the expense.

How remedy component differs from recalled component:

At this time, the remedy component has yet to be determined.

Identify how/when recall condition was corrected in production:

Reimbursement Plan

Description of reimbursement program:

Period of reimbursement:

Costs to be reimbursed:

Address for reimbursement claims:

Recall Schedule

Description of recall schedule:

** 2016 04 12 - Actual Phase 5 owner notification 2016 04 11.

**2016 03 22 - Target Phase 5 Owner notification - 3/31/2016

2/25/2016 Update: Stage 4: Final Owner Notification Begin Date: March 10, 2016.

** (Stage 4) Final Owner Notification Begin Date: Evaluate Part Supply Status in 4th Qtr 2016

** (Stage 5) Final Owner Notification Begin Date: Evaluate Part Supply Status in 1st Qtr 2017

Dealer Notification Begin Date: 6/8/2015

Dealer Notification End Date: TBD

Final Owner Notification (Stage 1) Begin Date: 6/8/2015

Part 573 Safety Recall Report**15V313**

Final Owner Notification (Stage 1) End Date: 6/19/2015

Interim Owner Notification (Stage 2-5) Begin Date: 6/15/2015

Interim Owner Notification (Stage 2-5) End Date: 7/13/2015

Final Owner Notification (Stage 2) Begin Date: 8/31/2015

Final Owner Notification (Stage 2) End Date: 8/31/2015

Final Owner Notification (Stage 3) Begin Date: 11/30/2015

Final Owner Notification (Stage 3) End Date: 11/30/2015

Final Owner Notification (Stage 4) Begin Date: TBD

Final Owner Notification (Stage 4) End Date: TBD

Final Owner Notification (Stage 5) Begin Date: TBD

Final Owner Notification (Stage 5) End Date: TBD

Planned Dealer Notification Date:

No Dealers

Planned Interim Owner Notification Date:

No Owners

Planned Remedy Owner Notification Date:

Phased Recall

Date when VIN will be searchable: