

Part 573 Safety Recall Report**15V-385****Manufacturer Name :** Jaguar Land Rover North America, LLC**Submission Date :** JUL 29,2015**NHTSA Recall No. :** 15V-385**Manufacturer Recall No. :** P068**Manufacturer Information :**

Manufacturer Name : Jaguar Land Rover North America, LLC

Address : 555 MACARTHUR BOLULEVARD

MAHWAH NJ 07430

Company phone : 201-760-8534

Population :

Number of potentially involved : 65,372

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2013-2016 Land Rover Range Rover

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : GAS

Descriptive Information : Land Rover Range Rover SUV in select VIN range

Production Dates : JUL 26, 2012 - MAR 09, 2015

VIN (Vehicle Identification Number) Range

Begin : SALGS2DF4DA000157

End : SALGS3KFXGA222280

 Not sequential VINs

Vehicle : 2014-2016 Land Rover Range Rover Sport

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : GAS

Descriptive Information : Land Rover Range Rover Sport SUV in select VIN range

Production Dates : FEB 18, 2013 - MAR 05, 2015

VIN (Vehicle Identification Number) Range

Begin : SALWR2WF0EA000002

End : SALWR2KF6GA619965

 Not sequential VINs**Description of Defect :**

Description of the Defect : A concern has been identified where customers have reported the door is unlatched when in the closed position and no indication provided of an unlatched condition. Some customers have reported that one door has opened while the vehicle was in motion.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Vehicle doors not latched in either the primary or secondary state may, during driving, open. This can increase the risk of a vehicle crash or compromise the safety of vehicle occupants.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : Brose Schließsysteme GmbH & Co.

Address : Kommanditgesellschaft

42369 Wuppertal-Ronsdorf FOREIGN STATES

Country : Germany

Chronology :

Attachment

Description of Remedy :

Description of Remedy Program : Owners will be notified and instructed to take their vehicle to Land Rover approved dealer who will download the latest software.

There will be no charge to owners for this repair.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Dealer/Owner notification as indicated.

Planned Dealer Notification Date : JUN 16, 2015 - JUN 16, 2015

Planned Owner Notification Date : AUG 07, 2015 - AUG 07, 2015

* NR - Not Reported