

Part 573 Safety Recall Report**15V-395****Manufacturer Name :** Entegra Coach**Submission Date :** JUN 17,2015**NHTSA Recall No. :** 15V-395**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Entegra Coach

Address : 903 South Main Street

P.O. Box 460 Middlebury IN 46540

Company phone : 1-800-945-4787

Population :

Number of potentially involved : 24

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2015-2015 Entegra Class A MH 39E Aspire

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Affected Units F13E8051 - F13E8074 - built on a Spartan MM Chassis

Production Dates : OCT 24, 2013 - FEB 11, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : per Spartan Chassis - the fasteners that attach the stay rod to the rear drive axle may not have been installed with thread locker or tightened in the correct sequence

FMVSS 1 :NR

FMVSS 2 :NR

Description of the Safety Risk : per Spartan - the fasteners may loosen and the stay rod could disconnect from the rear drive axle allowing the rear axle to move freely in certain directions. this could cause loss of vehicle control and increase risk of a crash.

Description of the Cause : Spartan has not provided the cause.

Identification of Any Warning that can Occur : per Spartan - the loosening of the fasteners may occur without warning.

Supplier Identification :**Component Manufacturer**

Name : Spartan Chassis

Address : 1541 Reynolds Road

Charlotte MICHIGAN 48813

Country : United States

Chronology :

6-15-15 Jayco received notification from Spartan Chassis regarding their recall(no # given) on the MM Chassis sold to Jayco Entegra Division regarding the rear axle V-rod. Included w the notification was a list of affected chassis that were matched to Entegra unit serial numbers to create the scope noted above.

Description of Remedy :

Description of Remedy Program : Per Spartan Chassis - the repair instructions are currently being compiled for publication - the fasteners that attach the stay rod to the rear axle will be removed and replaced with thread lock applied and tightened in the correct sequence at no charge to the owner. no time allowance noted at this time.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Jayco is prepared to release notification of the Recall once Spartan Chassis provides the repair instructions required

Planned Dealer Notification Date : JUL 17, 2015 - JUL 17, 2015

Planned Owner Notification Date : JUL 17, 2015 - JUL 17, 2015

* NR - Not Reported