

**Part 573 Safety Recall Report****15V-403****Manufacturer Name :** Spartan Motors USA**Submission Date :** JUL 20,2015**NHTSA Recall No. :** 15V-403**Manufacturer Recall No. :** 15011**Manufacturer Information :**

Manufacturer Name : Spartan Motors USA

Address : 1541 Reynolds Road

Charlotte MI 48813

Company phone : 517-543-6400

**Population :**

Number of potentially involved : 1,599

Estimated percentage with defect : 0

**Vehicle Information :**

Vehicle : 2010-2015 Spartan Motors Chassis Furion, Gladiator and MetroStar

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Incomplete vehicles affected by this recall are emergency response chassis cabs.

Production Dates : NOV 10, 2009 -JUN 16, 2015

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : The engine cooling fan may crack which may lead to separation of the fan blades separate.

FMVSS 1 :NR

FMVSS 2 :NR

Description of the Safety Risk : If this happens and a person is near the vicinity of the engine cooling fan, personal injury could occur.

Description of the Cause : The fan is not designed for the application.

Identification of Any Warning that can Occur : Fans could crack or blades could separate without warning.

**Supplier Identification :**

**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

**Chronology :**

Pending

**Description of Remedy :**

Description of Remedy Program : NR

How Remedy Component Differs from Recalled Component : A new engine cooling fan will be installed. The base plate on the new plate will be embossed.

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : JUN 26, 2015 - JUN 26, 2015

Planned Owner Notification Date : JUL 31, 2015 - JUL 31, 2015

\* NR - Not Reported