

Part 573 Safety Recall Report**15V-411****Manufacturer Name :** Newmar Corporation**Submission Date :** JUL 13,2015**NHTSA Recall No. :** 15V-411**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street

PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

Population :

Number of potentially involved : 96

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2015-2016 Newmar King Aire and Essex

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, fasteners that attach the stay rod to the rear drive axle may not have been installed with thread locker or tightened in the correct sequence.

The fasteners may loosen and the stay rod could disconnect from the rear drive axle allowing the rear axle to move freely in certain directions. This could cause loss of vehicle control which may increase the risk of a crash. The loosening of the fasteners may occur without warning.

Production Dates : MAR 13, 2014 - MAY 13, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2016-2016 Newmar Mountain Aire

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, fasteners that attach the stay rod to the rear drive axle may not have been installed with thread locker or tightened in the correct sequence.

The fasteners may loosen and the stay rod could disconnect from the rear drive axle allowing the rear axle to move freely in certain directions. This could cause loss of vehicle control which may increase the risk of a crash. The loosening of the fasteners may occur without warning.

Production Dates : MAR 17, 2015 - APR 17, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Description of Defect :

Description of the Defect : On certain motorhomes, fasteners that attach the stay rod to the rear drive axle may not have been installed with thread locker or tightened in the correct sequence. The fasteners may loosen and the stay rod could disconnect from the rear drive axle allowing the rear axle to move freely in certain directions. This could cause loss of vehicle control which may increase the risk of a crash. The loosening of the fasteners may occur without warning.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The fasteners may loosen and the stay rod could disconnect from the rear drive axle allowing the rear axle to move freely in certain directions. This could cause loss of vehicle control which may increase the risk of a crash. The loosening of the fasteners may occur without warning.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : Spartan Chassis

Address : 1541 Reynolds Rd.

Charlotte MICHIGAN 48813

Country : United States

Chronology :

NR

Description of Remedy :

Description of Remedy Program : Spartan Chassis, Inc. will be conducting this recall in its entirety. Fasteners that attach the stay rod to the rear drive axle may not have been installed with thread locker or tightened in the correct sequence.

Correction: Fasteners that attach the stay rod to the rear axle will be removed and replaced with thread lock applied. They will be tightened in the correct sequence. This will be done at no charge.

How Remedy Component Differs from Recalled Component : NR
Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : AUG 23, 2015 - NR

Planned Owner Notification Date : AUG 23, 2015 - NR

* NR - Not Reported