

Part 573 Safety Recall Report**15V-422****Manufacturer Name :** Van Hool N.V.**Submission Date :** JUN 26,2015**NHTSA Recall No. :** 15V-422**Manufacturer Recall No. :** P764**Manufacturer Information :**

Manufacturer Name : Van Hool N.V.

Address : BERNARD VAN HOOLSTRAAT 58

LIER-KONINGSHOOIKT (BELGIUM) 00 B2500

Company phone : 999

Population :

Number of potentially involved : 50

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2014-2015 VAN HOOL TD925

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : NUMBER OF PASSENGERS MAX 81

Production Dates : OCT 11, 2013 -DEC 12, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

☐ Not sequential VINs

Vehicle : 2015-2015 VAN HOOL TDX25

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : NUMBER OF PASSENGERS MAX. 81

Production Dates : DEC 23, 2014 -DEC 23, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

☐ Not sequential VINs**Description of Defect :**

Description of the Defect : The parameter of the Cummins engine for low idle speed is incorrectly set.

FMVSS 1 :NR

FMVSS 2 :NR

Description of the Safety Risk :In combination with high electrical demand and prolonged low idling, an alternator might overheat resulting in function loss and possible risk of fire.

Description of the Cause : NR
Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

NR

Description of Remedy :

Description of Remedy Program : Van Hool recalls all coaches from model year 2014 to 2015, in order to have the engine parameters settings for low idle speed immediately corrected by a qualified Cummins service technician. The alternators installed must be changed during the next scheduled preventive maintenance interval (at the latest in a month). Our designated agent ABC Bus, Inc. will notify Van Hool motorcoach owners of the above mentioned vehicles by mail sent to their addresses and conduct the recall free of charge.

How Remedy Component Differs from Recalled Component : The remedy low idle speed is 700 rpm.

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : JUN 26, 2015 - JUN 26, 2015

Planned Owner Notification Date : JUN 26, 2015 - JUN 26, 2015

* NR - Not Reported