



**Chronology :**

6 MAY 2015 - Autocar notified of first unit with overheated actuator condition. 15 MAY 2015 - Autocar notified of second unit with overheated actuator condition. 9 JUNE 2015 - Autocar notified of third unit with overheated actuator condition. 17 JUNE 2015 - Autocar started a root cause investigation. 24 JUNE 2015 - Autocar concluded investigation. 26 JUNE 2015 - Autocar decided to initiate a safety recall.

**Description of Remedy :**

Description of Remedy Program : Autocar will voluntarily initiate an owner notification and recall of all affected vehicles. Autocar will distribute to owners of affected vehicles an Owner Notification Letter which will describe the defect and provide instructions for scheduling repair of the vehicle at no cost to the owner.

How Remedy Component Differs from Recalled Component : An additional harness with four, one amp fuses will be added to the circuit.

Identify How/When Recall Condition was Corrected in Production : As of 7 JULY 2015, all units in production will receive the additional harness.

**Recall Schedule :**

Description of Recall Schedule : Owner notification letters will begin by 3 September, 2015 and completed by 24 September, 2015. Distributor notification will start and end on 3 September, 2015.

Planned Dealer Notification Date : SEP 03, 2015 - SEP 03, 2015

Planned Owner Notification Date : SEP 03, 2015 - SEP 24, 2015

\* NR - Not Reported