



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

15V444

Manufacturer Name: Chrysler (FCA US, LLC)

Submission Date: Jan 29, 2026

NHTSA Recall No.: 15V444

Manufacturer Recall No.: R37

Manufacturer Information

Population

Manufacturer Name: Chrysler (FCA US, LLC)

Address: 800 Chrysler Drive
CIMS 482-00-91
Auburn Hills MI, 48326-
2757

Total number of potentially involved: 88,460

Estimated percentage with defect: 1%

Vehicle Information

Vehicle 1: 2008-2010 Dodge Challenger

Product Category:

Product Type:

Fuel / Propulsion:

Production Dates: Sep 19, 2007 - Oct 29, 2010

Number of potentially involved:

Descriptive Information:

The 2008 - 2010 Dodge Challenger ("LC") vehicles being recalled are those equipped with Takata PSDI-4 front driver airbag inflators.

Defect / Noncompliance Description

Description of the defect or noncompliance:

On May 18, 2015, Takata submitted a 573 Safety Defect Information Report to NHTSA, "Takata has determined that a defect related to motor vehicle safety may arise in some of the subject inflators. The batwing-shaped propellant wafers in some of the subject inflators may experience an alteration over time, which could potentially lead to over-aggressive combustion in the event of an air bag deployment. Depending on the circumstances, this potential condition could create excessive internal pressure when the air bag is deployed, which could result in the body of the inflator rupturing upon deployment."

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

Part 573 Safety Recall Report

15V444

Per Takata's May 18, 2015 573 Safety Defect Information Report (15E-040), "in the event of an inflator rupture, metal fragments could pass through the air bag cushion material, which may result in injury or death to vehicle occupants."

Description of the cause:

Identification of any warning that can occur:

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name: Takata Corporation

Address: 2500 Takata Drive
Auburn Hills MI, 48326

Country: United States

Involved Components

Component Name 1:

Component Description:

Component Part Number:

Chronology

Please see the attached supplemental information titled "FCA US LLC Chronology - 2008-2010 LC Takata PSDI-4 – 07102015.pdf"

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Repair

Part 573 Safety Recall Report

15V444

Consumer Advisories: Do Not Drive Park Outside

Description of remedy program:

FCA US LLC ("FCA US") will conduct a voluntary safety recall on all affected vehicles to replace the front driver airbag inflator.

FCA US has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, FCA US, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the company for confirmation of the expense.

How remedy component differs from recalled component:

Identify how/when recall condition was corrected in production:

Reimbursement Plan

Description of reimbursement program:

Period of reimbursement:

Costs to be reimbursed:

Address for reimbursement claims:

Recall Schedule

Description of recall schedule:

Planned Dealer Notification Date (VINs live): 7/27/2015
 Planned Interim Owner Letter Notification Begin Date: 8/14/2015
 Planned Interim Owner Letter Notification End Date: 8/21/2015
 ****11-24-2015
 Planned Dealer Notification Date (Repair): 11/11/2015
 Planned Final Owner Letter Notification Begin Date: 11/17/2015
 Planned Final Owner Letter Notification End Date: 11/20/2015

Planned Dealer Notification Date: No Dealers

Planned Interim Owner Notification Date: No Owners

Planned Remedy Owner Notification Date: Phased Recall

Part 573 Safety Recall Report

15V444

Date when VIN will be searchable: