

Part 573 Safety Recall Report

15V-492

Manufacturer Name : Newmar Corporation

Submission Date : MAY 06, 2016

NHTSA Recall No. : 15V-492

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street
PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

Population :

Number of potentially involved : 82

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2015-2015 Newmar Essex and King Aire

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain units, the control module for the air suspension may experience a loss of power resulting in the air suspension not being able to achieve ride height. If the ride height of the suspension is less than specified ride height, negative impact to roll steer could occur. This could cause the vehicle to be difficult to control and increase the risk of a crash. This could occur without warning.

Production Dates : MAR 07, 2014 - JUN 15, 2015

VIN Range 1 : Begin : NR

End : NR

☐ Not sequential

Vehicle 2 : 2016-2016 Newmar Mountain Aire; Essex and King Aire

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain units, the control module for the air suspension may experience a loss of power resulting in the air suspension not being able to achieve ride height. If the ride height of the suspension is less than specified ride height, negative impact to roll steer could occur. This could cause the vehicle to be difficult to control and increase the risk of a crash. This could occur without warning.

Production Dates : MAR 09, 2015 - JUN 05, 2015

VIN Range 1 : Begin : NR

End : NR

☐ Not sequential

Description of Defect :

Description of the Defect : On certain units, the control module for the air suspension may experience a loss of power resulting in the air suspension not being able to achieve ride height. If the ride height of the suspension is less than specified ride height, negative impact to roll steer could occur. This could cause the vehicle to be difficult to control and increase the risk of a crash. This could occur without warning.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the ride height of the suspension is less than specified ride height, negative impact to roll steer could occur. This could cause the vehicle to be difficult to control and increase the risk of a crash. This could occur without warning.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : Spartan Motors, Inc.

Address : NR

NR

Country : NR

Chronology :

7/23/2015; Newmar Corporation received notification of a potential equipment defect relating to motor vehicle safety that may exist in specific Hadley interface modules identified as potentially defective by Spartan Motors, Inc.

07/31/2015 Newmar sent Notice of Defect to NHTSA.

Description of Remedy :

Description of Remedy Program : Spartan Motors will provide owners of all affected motor homes a remedy for the potential defect at no charge for parts or labor. This remedy consists of: an independent electrical circuit that supplies power to the control module will be provided at no charge.

How Remedy Component Differs : The original control module for the air suspension may experience a loss of power resulting in the air suspension not being able to achieve the

from Recalled Component : appropriate ride height.
Identify How/When Recall Condition NR
was Corrected in Production :

Recall Schedule :

Description of Recall Schedule : NR
Planned Dealer Notification Date : NR - NR
Planned Owner Notification Date : NR - NR

* NR - Not Reported