

Part 573 Safety Recall Report**15V-541****Manufacturer Name :** Chrysler (FCA US LLC)**Submission Date :** NOV 10,2015**NHTSA Recall No. :** 15V-541**Manufacturer Recall No. :** R46**Manufacturer Information :**

Manufacturer Name : Chrysler (FCA US LLC)

Address : 800 Chrysler Drive

CIMS 482-00-91 Auburn Hills MI 48326-2757

Company phone : 1-800-853-1403

Population :

Number of potentially involved : 149,512

Estimated percentage with defect : 1

Vehicle Information :

Vehicle : 2013-2014 Ram 3500

Vehicle Type :

Body Style : PICKUP TRUCK

Power Train : NR

Descriptive Information : Certain 2013 MY and 2014 MY Ram 3500 vehicles.

Production Dates : OCT 09, 2012 - JUL 29, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2014-2014 Ram 3500 Cab Chassis

Vehicle Type :

Body Style : PICKUP TRUCK

Power Train : NR

Descriptive Information : Certain 2014MY Ram 3500 vehicles.

Production Dates : OCT 09, 2012 - JUL 29, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2014-2014 Ram 2500

Vehicle Type :

Body Style : PICKUP TRUCK

Power Train : NR

Descriptive Information : Certain 2014MY Ram 2500 vehicles.

Production Dates : OCT 09, 2012 - JUL 29, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Vehicles may have front track bar frame bracket welds with inadequate fusion which may cause the bracket components to separate from the frame.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : This defect may, in certain cases, result in diminished steering response.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : Metalsa

Address : Fracc. Parque Industrial Sta. Mónica

Lote M1 Carretera Estatal #105 Saltillo FOREIGN STATES 25079

Country : Mexico

Chronology :

Please see the attached supplemental information titled "FCA US LLC Chronology - R46 2013 2014 D2 2014 DJ DD Track Bar Bracket 08252015.pdf".

On August 18, 2015, FCA US determined, through the Vehicle Regulations Committee, to conduct a voluntary safety recall of the affected vehicles.

Description of Remedy :

Description of Remedy Program : FCA US will conduct a voluntary safety recall on all affected vehicles; remedy will be documented once testing is complete.

FCA US has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, FCA US, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the company for confirmation of the expense.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : 11/10/15: FCA US will notify dealers 11/9/15 of inspection process and interim owner letter. Owner letters will be mailed 11/16/15.**

Planned Dealer Notification: 10/02/2015, interim letter notification and VINS active.

Planned Interim Owner Notification Start / End Date: 10/24/2015 - 10/24/2015, interim owner letter notification

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported