

Part 573 Safety Recall Report

15V-549

Manufacturer Name : Spartan Motors USA

Submission Date : DEC 22, 2017

NHTSA Recall No. : 15V-549

Manufacturer Recall No. : 15014



Manufacturer Information :

Manufacturer Name : Spartan Motors USA

Address : 1541 Reynolds Road

Charlotte MI 48813

Company phone : 517-543-6400

Population :

Number of potentially involved : 1,212

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2004-2008 Spartan Specialty Vehicle K2, K3, and MM

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : Chassis affected by this defect information report were to be complete as motor home chassis.

Production Dates : MAR 17, 2003 - MAR 15, 2007

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : Engine cooling fans may separate from the fan drive.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the engine area is open and the cooling fan is operating and detaches, someone in close proximity of the engine cooling fan may be injured.

Description of the Cause : NR

Identification of Any Warning that can Occur : The engine cooling fan may separate without warning.

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

Country : NR

Chronology :

In March 2007, Spartan released a technical service bulletin related to the condition subject to this recall. In March 2013, Spartan responded to a request from ODI to submit all technical service bulletins released in the 10 years prior by submitting the document from March 2007. In August 2013, ODI request field reports, customer complaints, and warranty claims for each of those service bulletins which includes the service bulletin released related to this recall. On July 8, 2015, Spartan agreed to submit a defect information report for the issue addressed by the original service bulletin.

Description of Remedy :

Description of Remedy Program :	Engine cooling fans may detach from the fan drive due to multiple problems within the fan drive system.
How Remedy Component Differs from Recalled Component :	Fan drives, and other components, may be replaced depending on the configuration of the fan drive system.
Identify How/When Recall Condition was Corrected in Production :	This fan drive system is no longer in production.

Recall Schedule :

Description of Recall Schedule :	Notifications deferred to 23OCT15
Planned Dealer Notification Date :	OCT 02, 2015 - OCT 02, 2015
Planned Owner Notification Date :	OCT 23, 2015 - OCT 23, 2015

* NR - Not Reported