

Part 573 Safety Recall Report**15V-549****Manufacturer Name :** Spartan Motors USA**Submission Date :** OCT 14,2015**NHTSA Recall No. :** 15V-549**Manufacturer Recall No. :** 15014**Manufacturer Information :**

Manufacturer Name : Spartan Motors USA

Address : 1541 Reynolds Road

Charlotte MI 48813

Company phone : 517-543-6400

Population :

Number of potentially involved : 1,212

Estimated percentage with defect : 0

Vehicle Information :

Vehicle : 2004-2008 Spartan Specialty Vehicle K2, K3, and MM

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : Chassis affected by this defect information report were to be complete as motor home chassis.

Production Dates : MAR 17, 2003 - MAR 15, 2007

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Engine cooling fans may separate from the fan drive.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the engine area is open and the cooling fan is operating and detaches, someone in close proximity of the engine cooling fan may be injured.

Description of the Cause : NR

Identification of Any Warning that can Occur : The engine cooling fan may separate without warning.

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

In August 2013, Office of Defects Investigation requested information on service bulletins related to this issue that were previously submitted by Spartan to NHTSA. In September 2013, Spartan submitted the requested information. On July 8, 2015, Spartan agreed to submit a defect information report for the issue addressed by the service bulletins.

Description of Remedy :

Description of Remedy Program : Engine cooling fans may detach from the fan drive due to multiple problems within the fan drive system.

How Remedy Component Differs from Recalled Component : Fan drives, and other components, may be replaced depending on the configuration of the fan drive system.

Identify How/When Recall Condition was Corrected in Production : This fan drive system is no longer in production.

Recall Schedule :

Description of Recall Schedule : Notifications deferred to 23OCT15

Planned Dealer Notification Date : OCT 02, 2015 - OCT 02, 2015

Planned Owner Notification Date : OCT 23, 2015 - OCT 23, 2015

* NR - Not Reported