

Part 573 Safety Recall Report**15V-551****Manufacturer Name :** Foretravel, Inc.**Submission Date :** SEP 10,2015**NHTSA Recall No. :** 15V-551**Manufacturer Recall No. :** 15V551**Manufacturer Information :**

Manufacturer Name : Foretravel, Inc.

Address : 1221 N.W. Stallings Drive

Nacogdoches TX 75964

Company phone : 936-564-8367

Population :

Number of potentially involved : 37

Estimated percentage with defect : 0

Vehicle Information :

Vehicle : 2012-2014 Foretravel Nimbus, Phenix, IH45

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : Class A motorhome

Production Dates : MAY 16, 2011 - FEB 24, 2014

VIN (Vehicle Identification Number) Range

Begin : 1F98DN427CN054972

End : 1F98DP457EN054009

☐ Not sequential VINs**Description of Defect :**

Description of the Defect : Reyco Granning has learned that IFS modules manufactured during the affected timeframe could contain loose ball joints.

NHTSA ID 15E067

FMVSS 1 :NR

FMVSS 2 :NR

Description of the Safety Risk :If loose ball joints are not detected, they may eventually separate from their mating part, which could result in a partial loss of steering control.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : Reyco Granning

Address : 3216 Olympia Dr. Suite C & D
Lafayette INDIANA 47909

Country : United States

Chronology :

NR

Description of Remedy :

Description of Remedy Program : See attached document

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :Description of Recall Schedule : Dealer letters and customer letters will be mailed from 10/19/2015 thru
11/02/2015

Planned Dealer Notification Date : OCT 19, 2015 - NOV 02, 2015

Planned Owner Notification Date : OCT 19, 2015 - NOV 02, 2015

* NR - Not Reported