

Part 573 Safety Recall Report**15V-571****Manufacturer Name :** Jaguar Land Rover North America, LLC**Submission Date :** SEP 10,2015**NHTSA Recall No. :** 15V-571**Manufacturer Recall No. :** P071**Manufacturer Information :**

Manufacturer Name : Jaguar Land Rover North America, LLC

Address : 555 MACARTHUR BOLULEVARD

MAHWAH NJ 07430

Company phone : 201-760-8534

Population :

Number of potentially involved : 5,914

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2014-2014 Land Rover Range Rover Sport

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : GAS

Descriptive Information : 2014 Land Rover Range Rover Sport in selected VIN Range.

Production Dates : DEC 16, 2013 - APR 15, 2014

VIN (Vehicle Identification Number) Range

Begin : SALWR2WFXEA339933

End : SALWR2TF0EA368586

 Not sequential VINs**Description of Noncompliance :**

Description of the Noncompliance : A non-compliance concern has been identified on certain 2014MY Land Rover Range Rover Sport vehicles where the owner's handbook information, which details the functionality of the Airbag Status Indicator Lamp, has been incorrectly described. Actual operation of Occupant Sensor System (OSS) is not affected, however the description of operation in the owner's handbook does not correspond with the actual Airbag Status Indicator Lamp operation. Vehicles with the handbook in this condition will not comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) 208 – Occupant Crash Protection.

FMVSS 1 : 208 - Occupant crash protection

FMVSS 2 : NR

Description of the Safety Risk : An occupant that does not correctly understand airbag functionality may be at increased risk of injury in a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

Engineering reviews of draft 2016MY handbook descriptions identified that the operation of the Airbag Status Indicator Lamp differed to the actual operation of the system. Jaguar Land Rover undertook a thorough review of all previous hand book descriptions for this system operation and confirmed that this anomaly only exists for certain 2014MY vehicles. 2015MY hand book description was reviewed at 2015MY vehicle introduction and is correct to system operation.

Jaguar Land Rover investigations identified the concern was linked to the introduction of a functional change where the Airbag Status Indicator Lamp was incorporated into a new roof console system.

The Senior Review Panel reviewed the concern on September 3, 2015, and concluded that the condition represented a non-compliance with FMVSS 208 and that a non-compliance recall action is launched to remedy all the affected vehicles.

There have been no reports of accidents or injuries as a result of this concern.

Description of Remedy :

Description of Remedy Program : Jaguar Land Rover will distribute a handbook supplement to all affected owners. The handbook supplement will correspond with the correct Occupant Sensor system operation.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : SEP 15, 2015 - SEP 15, 2015

Planned Owner Notification Date : OCT 31, 2015 - OCT 31, 2015

* NR - Not Reported