

Part 573 Safety Recall Report**15V-575****Manufacturer Name :** Vermeer Manufacturing Company**Submission Date :** SEP 11,2015**NHTSA Recall No. :** 15V-575**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Vermeer Manufacturing Company

Address : 1210 VERMEER ROAD EAST

PO BOX 200 PELLA IA 50219-0200

Company phone : 641-628-3141

Population :

Number of potentially involved : 0

Estimated percentage with defect : 0

Vehicle Information :

Vehicle : 2008-2016 VERMEER BC1000XL

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Brush chipper-single axle trailer

Production Dates : MAR 28, 2008 - SEP 30, 2015

VIN (Vehicle Identification Number) Range

Begin : 1VRY1119X81011001

End : 1VRY11195A1012028

 Not sequential VINs

Begin : 1VRY1119691015001

End : 1VRY11195G1022907

 Not sequential VINs

Vehicle : 2013-2016 VERMEER BC700XL

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Brush Chipper-single axle trailer

Production Dates : OCT 09, 2013 - SEP 30, 2015

VIN (Vehicle Identification Number) Range

Begin : 1VRC101V7E1000101

End : 1VRC101V7G1001025

 Not sequential VINs

Vehicle : 2012-2016 VERMEER BC900XL

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Brush Chipper- single-axle trailer

Production Dates : JUN 08, 2012 - SEP 30, 2015

VIN (Vehicle Identification Number) RangeBegin : 1VR712163C1000101 End : 1VR712169F1000544 Not sequential VINsBegin : 1VR712163F1002001 End : 1VR712166G1002060 Not sequential VINs

Vehicle : 2009-2016 VERMEER BC1200XL

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Brush Chipper- Single-axle trailer

Production Dates : JUL 24, 2009 - SEP 30, 2016

VIN (Vehicle Identification Number) RangeBegin : 1VR7141Y691000101 End : 1VR7141Y4C1000492 Not sequential VINsBegin : 1VR7141Y8C1001001 End : 1VR7141YXG1001555 Not sequential VINs

Vehicle : 2003-2016 VERMEER BC1800XL

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Brush Chipper- Single-axle trailer

Production Dates : OCT 08, 2003 - SEP 30, 2015

VIN (Vehicle Identification Number) RangeBegin : 1VRY131Z831000101 End : 1VRY131Z071001698 Not sequential VINsBegin : 1VRY131Z671002001 End : 1VRY131Z8D1003291 Not sequential VINsBegin : 1VRY131Z2C1004001 End : 1VRY131Z6G1004797 Not sequential VINsBegin : 1VRY151Z1F1006001 End : 1VRY151Z7F1006004 Not sequential VINs

Vehicle : 2005-2014 VERMEER BC600XL

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Brush Chipper- Single-axle trailer

Production Dates : JUL 18, 2005 - NOV 08, 2013

VIN (Vehicle Identification Number) RangeBegin : 1VR2091H051000101 End : 1VR2091H0E1005346 Not sequential VINs

Vehicle : 2005-2016 VERMEER SC802

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Stump Cutter- Single-axle trailer

Production Dates : JUL 06, 2005 - SEP 30, 2015

VIN (Vehicle Identification Number) Range

Begin : 1VR2151JX51000101 End : 1VR2151J891000412 Not sequential VINs

Begin : 1VR2151J391001001 End : 1VR2151J2F1001339 Not sequential VINs

Begin : 1VR2151J3F1002001 End : 1VR2151J7G1002049 Not sequential VINs

Vehicle : 2005-2013 VERMEER SC602

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Stump Cutter- Single-axle trailer

Production Dates : JAN 27, 2005 - JUL 17, 2013

VIN (Vehicle Identification Number) Range

Begin : 1VR2141D641000101 End : 1VR2141D791000471 Not sequential VINs

Begin : 1VR2141D3B1002000 End : 1VR2141D2D1002122 Not sequential VINs

Description of Noncompliance :

Description of the Noncompliance : The side marker LED lights installed during manufacturing did not include reflex reflector built into the lens and no other reflex reflectors were installed on sides of trailers.

FMVSS 1 : 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS 2 : NR

Description of the Safety Risk : The machine may not be visible from the side at night if the side marker lights have failed.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

8-Sept-2015 confirmed that the installed LED side marker lights (amber and/or red) did not include reflex reflector capability and the lens were not marked with the SAE lens coding (A).

Description of Remedy :

Description of Remedy Program : A field campaign will be initiated to install separate reflex reflectors (amber and/or red) with an SAE (A) marking will be installed on the sides of each of the affected machines.

How Remedy Component Differs from Recalled Component : The reflex reflectors with an SAE (A) marking will be present on the side of the machine.

Identify How/When Recall Condition was Corrected in Production : Separate reflex reflectors with SAE (A) marking or the LED side marker lights with reflex reflector with SAE (A) rated lens will be installed on machines as quickly as possible in September 2015. Actual date dependent on parts availability.

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported