

Part 573 Safety Recall Report**15V-585****Manufacturer Name :** Newmar Corporation**Submission Date :** SEP 14,2015**NHTSA Recall No. :** 15V-585**Manufacturer Recall No. :** 15V-554**Manufacturer Information :**

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street

PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

Population :

Number of potentially involved : 165

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2010-2010 Newmar Dutch Star

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, If the exhaust tube tears, hot exhaust gas could blow against other components or material. If exhaust gas temperatures exceed the flash point of other material or components, it could increase the risk of fire. This may occur without warning.

Production Dates : MAY 13, 2009 - APR 14, 2010

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2010-2010 Newmar Dutch Aire

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : If the exhaust tube tears, hot exhaust gas could blow against other components or material. If exhaust gas temperatures exceed the flash point of other material or components, it could increase the risk of fire. This may occur without warning.

Production Dates : MAY 12, 2009 - FEB 08, 2010

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2012-2013 Newmar King Aire

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : If the exhaust tube tears, hot exhaust gas could blow against other components or material. If exhaust gas temperatures exceed the flash point of other material or components, it could increase the risk of fire. This may occur without warning.

Production Dates : MAR 22, 2011 - MAY 17, 2013

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Description of Defect :

Description of the Defect : If the exhaust tube tears, hot exhaust gas could blow against other components or material. If exhaust gas temperatures exceed the flash point of other material or components, it could increase the risk of fire. This may occur without warning.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If exhaust gas temperatures exceed the flash point of other material or components, it could increase the risk of fire. This may occur without warning.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : Spartan Motors, Inc.

Address : 1541 Reynolds Rd.

Charlotte MICHIGAN 48813

Country : United States

Chronology :

NR

Description of Remedy :

Description of Remedy Program : Spartan Motors, Inc. Remedy: A new exhaust tube will be supplied, and installed, free of charge.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NOV 13, 2015 - NR

Planned Owner Notification Date : NOV 13, 2015 - NR

* NR - Not Reported