

Part 573 Safety Recall Report**15V-591****Manufacturer Name :** Blue Bird Body Company**Submission Date :** SEP 21,2015**NHTSA Recall No. :** 15V-591**Manufacturer Recall No. :** R15YG-SB**Manufacturer Information :**

Manufacturer Name : Blue Bird Body Company

Address : P.O. Box 937

402 Blue Bird Boulevard Fort Valley GA 31030

Company phone : 478-822-2242

Population :

Number of potentially involved : 2

Estimated percentage with defect : 0

Vehicle Information :

Vehicle : 2016-2016 Blue Bird Vision (BBCV)

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : The Engine Control Module (ECM) may develop an internal electrical short circuit that could possibly blow a fuse in the ECM's electrical supply circuit, resulting in an engine stall without warning. If this occurs, the engine cannot be restarted until the ECM and fuse are replaced.

Production Dates : AUG 16, 2015 - AUG 16, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : The Engine Control Module (ECM) may develop an internal electrical short circuit that could possibly blow a fuse in the ECM's electrical supply circuit, resulting in an engine stall without warning. If this occurs, the engine cannot be restarted until the ECM and fuse are replaced.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : An unexpected engine stall without the ability to restart the engine may lead to an increased risk of a crash.

Description of the Cause : An internal short circuit may have been caused when Printed Circuit Boards (PCB's) were potentially damaged during assembly of the PCB's to the ECM case during ECM production.

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : Cummins, Incorporated

Address : 301 Washington Street
Columbus INDIANA 47202

Country : United States

Chronology :

September 16, 2015, Cummins notified Blue Bird of the potential risk to the circuit boards on some engine ECM's they supplied to Blue Bird and their decision to declare a recall.

September 17, 2015, Blue Bird agreed to issue a recall to address the issue.

Description of Remedy :

Description of Remedy Program : Cummins will replace the existing ECM with a new (remedy) ECM.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : OCT 22, 2015 - OCT 22, 2015

Planned Owner Notification Date : OCT 22, 2015 - OCT 22, 2015

* NR - Not Reported