

Part 573 Safety Recall Report**15V-594****Manufacturer Name :** Mitsubishi Motors North America, Inc.**Submission Date :** SEP 22,2015**NHTSA Recall No. :** 15V-594**Manufacturer Recall No. :** SR-15-011**Manufacturer Information :**

Manufacturer Name : Mitsubishi Motors North America, Inc.

Address : 6400 Katella Avenue

Cypress CA 90630

Company phone : 714-372-6000

Population :

Number of potentially involved : 16,455

Estimated percentage with defect : NR

Vehicle Information :

Vehicle : 2014-2014 Mitsubishi MIRAGE

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : Only vehicles manufactured within the specified production dates are affected by this recall.

Production Dates : JUL 27, 2013 - NOV 20, 2013

VIN (Vehicle Identification Number) Range

Begin : ML32A4HJ5EH000209

End : ML32A3HJ4EH014502

 Not sequential VINs

Vehicle : 2012-2012 Mitsubishi i-MiEV

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : HYBRID ELECTRIC

Descriptive Information : Only vehicles manufactured within the specified production dates are affected by this recall.

Production Dates : OCT 28, 2011 - JAN 10, 2013

VIN (Vehicle Identification Number) Range

Begin : JA3215H10CU008563

End : JA3215H4XDU606851

 Not sequential VINs**Description of Defect :**

Description of the Defect : Due to an improper manufacturing process control, the electrical resistance inside the impact sensor for the SRS air bag system may have increased. As a result, abnormal communication may be detected by the ECU causing the SRS warning lamp to illuminate. If a vehicle is involved in a collision necessitating frontal, side,

and/or curtain air bag deployment when the SRS warning lamp is illuminated, frontal air bag deployment could be delayed and/or the side and curtain air bag may not deploy.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Delayed frontal air bag deployment and/or non-deployment of the side and curtain air bag increases the risk of injury.

Description of the Cause : NR

Identification of Any Warning that can Occur : SRS warning lamp will illuminate.

Supplier Identification :

Component Manufacturer

Name : MITSUBISHI ELECTRIC CORPORATION

Address : Miwa 2-3-33

Sanda FOREIGN STATES 669-1513

Country : Japan

Chronology :

See attached document.

Description of Remedy :

Description of Remedy Program : Owners of all affected vehicles will be notified and encouraged to bring in their vehicles for SRS impact sensor replacements with a countermeasure unit. This replacement would be completed free of charge. Owners seeking reimbursement for any expenses associated with this recall will be directed in the notification letter to contact the Mitsubishi Customer Relations Department for instructions on how to apply for a refund.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : MMNA is working internally to determine the dealer and customer notification date and will update accordingly.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported