

Part 573 Safety Recall Report**15V-617****Manufacturer Name :** Daimler Trucks North America LLC**Submission Date :** SEP 29,2015**NHTSA Recall No. :** 15V-617**Manufacturer Recall No. :** FL-693**Manufacturer Information :**

Manufacturer Name : Daimler Trucks North America LLC

Address : 4747 N. Channel Avenue

Portland OR 97217-3849

Company phone : 800-745-8000

Population :

Number of potentially involved : 14

Estimated percentage with defect : 10

Vehicle Information :

Vehicle : 2015-2016 Freightliner Cascadia

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Vehicles manufactured with certain Eaton Fuller FR 10-speed manual transmissions

Production Dates : JAN 04, 2015 - APR 24, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2015-2016 Freightliner Business Class M2

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Vehicles manufactured with certain Eaton Fuller FR 10-speed manual transmissions

Production Dates : JAN 04, 2015 - APR 24, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2015-2016 Freightliner 108SD

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Vehicles manufactured with certain Eaton Fuller FR 10-speed manual transmissions

Production Dates : JAN 04, 2015 - APR 24, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Vehicle : 2015-2016 Freightliner 114SD

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Vehicles manufactured with certain Eaton Fuller FR 10-speed manual transmissions

Production Dates : JAN 04, 2015 - APR 24, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Vehicle : 2015-2016 Western Star 4700

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Vehicles manufactured with certain Eaton Fuller FR 10-speed manual transmissions

Production Dates : JAN 04, 2015 - APR 24, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Description of Defect :

Description of the Defect : Eaton has reported that "When the transmission shift lever is moved from reverse to neutral, the reverse gear may stay engaged. When the transmission shift lever is moved from reverse to a forward gear position, the transmission may mechanically lock (i.e., both the reverse gear and forward gear engage simultaneously)." See attached Eaton Corporation recall.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Eaton has reported "When shifting the transmission from reverse to neutral, the recall condition may result in a crash without prior warning."

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : Eaton Corporation

Address : 1000 Eaton Blvd

Cleveland OHIO 44122

Country : United States

Chronology :

In September 2015, Eaton Corporation Notified DTNA that it had determined a defect existed in certain FR transmissions. DTNA decided to conduct a voluntary safety recall on vehicles equipped with suspect transmissions

Description of Remedy :

Description of Remedy Program : Transmissions will be inspected and repaired as necessary. Repairs will be performed by Daimler Trucks North America authorized service facilities. Copies of the reimbursement plan will be submitted as a supplemental report when available.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Customer notification will be by first class mail using Daimler Trucks North America records to determine the customers affected

Planned Dealer Notification Date : NOV 28, 2015 - NOV 28, 2015

Planned Owner Notification Date : NOV 28, 2015 - NOV 28, 2015

* NR - Not Reported