

Part 573 Safety Recall Report**15V-623****Manufacturer Name :** Daimler Trucks North America LLC**Submission Date :** SEP 30,2015**NHTSA Recall No. :** 15V-623**Manufacturer Recall No. :** FL-690**Manufacturer Information :**

Manufacturer Name : Daimler Trucks North America LLC

Address : 4747 N. Channel Avenue

Portland OR 97217-3849

Company phone : 800-745-8000

Population :

Number of potentially involved : 4

Estimated percentage with defect : 0

Vehicle Information :

Vehicle : 2016-2016 Thomas Built Bus Saf-T-Liner C2

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : Thomas Built School Busses equipped with Cummins ISB 6.7 engines.

Production Dates : AUG 06, 2015 - AUG 20, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Cummins Inc has reported that "The Engine Control Module (ECM) may develop an internal electrical short circuit that could possibly blow a fuse in the ECM's electrical supply circuit, resulting in an engine stall without warning. If this occurs, the engine cannot be restarted until the ECM and fuse are replaced."

See attached Cummins Inc defect information report NHTSA recall 15E-073.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Cummins Inc has reported that "An unexpected engine stall without the ability to restart the engine may lead to an increased risk of a crash."

See attached Cummins Inc defect information report NHTSA recall 15E-073.

Description of the Cause :

Identification of Any Warning that can Occur :

Supplier Identification :**Component Manufacturer**

Name : Cummins Inc

Address : 500 Jackson St

Columbus INDIANA 47201

Country : United States

Chronology :

September 2015 - Cummins notified DTNA of NHTSA recall 15E-073

September 2015 - DTNA decided to initiate a voluntary safety recall

Description of Remedy :

Description of Remedy Program : Cummins Inc is conducting this recall. Cummins will replace the existing ECM with a new (remedy) ECM. Repairs will be performed by Cummins authorized service facilities. See attached Cummins Inc Defect Information Report NHTSA Recall 15E-073
See attached Cummins Inc defect information report NHTSA recall 15E-073.

How Remedy Component Differs from Recalled Component :

Identify How/When Recall Condition was Corrected in Production :

Recall Schedule :

Description of Recall Schedule :

Planned Dealer Notification Date : NOV 28, 2015 - NOV 28, 2015

Planned Owner Notification Date : NOV 28, 2015 - NOV 28, 2015

* NR - Not Reported