

Part 573 Safety Recall Report

15V-654

Manufacturer Name : Newmar Corporation**Submission Date :** MAY 06, 2016**NHTSA Recall No. :** 15V-654**Manufacturer Recall No. :** 15V-548**Manufacturer Information :****Population :**

Manufacturer Name : Newmar Corporation

Number of potentially involved : 119

Address : 355 North Delaware Street

Estimated percentage with defect : 100 %

PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

Vehicle Information :

Vehicle 1 : 2007-2008 Newmar Mountain Aire

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, Tag axle wheel bearings may overheat. Overheating of the tag axle may be detected by distortion or melting of the Stemco cover or ABS lamp illumination. If the wheel bearings overheat, there may be an increased risk of a wheel end fire with the possibility of a personal injury or vehicle crash.

Production Dates : OCT 16, 2006 - JUL 24, 2007

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2007-2008 Newmar Dutch Star

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, Tag axle wheel bearings may overheat. Overheating of the tag axle may be detected by distortion or melting of the Stemco cover or ABS lamp illumination. If the wheel bearings overheat, there may be an increased risk of a wheel end fire with the possibility of a personal injury or vehicle crash.

Production Dates : OCT 12, 2006 - JUN 29, 2007

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 3 : 2007-2008 Newmar Essex

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, Tag axle wheel bearings may overheat. Overheating of the tag axle may be detected by distortion or melting of the Stemco cover or ABS lamp illumination. If the wheel bearings overheat, there may be an increased risk of a wheel end fire with the possibility of a personal injury or vehicle crash.

Production Dates : NOV 01, 2006 - MAY 24, 2007

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : On certain motorhomes, Tag axle wheel bearings may overheat. Overheating of the tag axle may be detected by distortion or melting of the Stemco cover or ABS lamp illumination. If the wheel bearings overheat, there may be an increased risk of a wheel end fire with the possibility of a personal injury or vehicle crash.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the wheel bearings overheat, there may be an increased risk of a wheel end fire with the possibility of a personal injury or vehicle crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : Spartan Motors, Inc.

Address : 1541 Reynolds Rd.
Charlotte MICHIGAN 48813

Country : United States

Chronology :

10/07/2015; Newmar Corporation received notification of a potential equipment defect relating to motor vehicle safety that may exist in specific tag axle wheel bearings on Spartan Chassis identified as potentially defective by Spartan Motors, Inc.

10/13/2015 Newmar sent Notice of Defect to NHTSA

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs
from Recalled Component : NR

Identify How/When Recall Condition
was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : DEC 11, 2015 - NR

Planned Owner Notification Date : DEC 11, 2015 - NR

* NR - Not Reported