OMB Control No.: 2127-0004

# **Part 573 Safety Recall Report**

## 15V-676

**Manufacturer Name :** Chrysler (FCA US LLC)

Submission Date: OCT 15,2015 NHTSA Recall No.: 15V-676 Manufacturer Recall No.: R57



#### **Manufacturer Information:**

Manufacturer Name: Chrysler (FCA US LLC)

Address: 800 Chrysler Drive

CIMS 482-00-91 Auburn Hills MI 48326-2757

Company phone: 1-800-853-1403

### **Population:**

Number of potentially involved: 75,574 Estimated percentage with defect: 1

#### **Vehicle Information:**

Vehicle: 2015-2015 Jeep Cherokee

Vehicle Type : Body Style : SUV Power Train : NR

Descriptive Information: Certain MY 2015 Jeep Cherokee vehicles equipped with the 2.4L engine (Sales

Code ED6 or ED8)

 $Production\ Dates: OCT\ 01,\ 2014\ -JUN\ 18,\ 2015$ 

**VIN (Vehicle Identification Number) Range** 

Begin: NR End: NR Not sequential VINs

#### **Description of Defect:**

Description of the Defect: Some 2015 MY Jeep Cherokee ("KL") vehicles may experience a misrouted A/C

suction/discharge combo line. A misrouted A/C combo line can be pinched and cut or thermally degraded by the exhaust manifold heat shield, potentially resulting in

loss of air conditioning and the presence of smoke and/or fire.

FMVSS 1 :NR FMVSS 2 :NR

Description of the Safety Risk: This defect may, in certain cases, result in smoke and/or fire.

Description of the Cause: NR

Identification of Any Warning that can Occur: NR

## **Supplier Identification:**

**Component Manufacturer** 

Name: NR Address: NR

Country: NR

### **Chronology:**

Please see the attached supplemental information titled "FCA US LLC Chronology - KL AC Line 10152015.pdf".

### **Description of Remedy:**

Description of Remedy Program: Conduct a voluntary safety recall on all affected vehicles, to inspect for

misrouted A/C suction discharge combo lines, and replace those found to be

misrouted.

FCA US has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, FCA US, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the company for confirmation of the expense.

How Remedy Component Differs from Recalled Component : NR Identify How/When Recall Condition was Corrected in Production : NR

#### **Recall Schedule:**

Description of Recall Schedule : 10/15/15: FCA US will provide a dealer notification and owner notification

schedule once established.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date: NR - NR

\* NR - Not Reported