

**Part 573 Safety Recall Report****15V-676****Manufacturer Name :** Chrysler (FCA US LLC)**Submission Date :** FEB 23, 2016**NHTSA Recall No. :** 15V-676**Manufacturer Recall No. :** R57**Manufacturer Information :**

Manufacturer Name : Chrysler (FCA US LLC)

Address : 800 Chrysler Drive

CIMS 482-00-91 Auburn Hills MI 48326-2757

Company phone : 1-800-853-1403

**Population :**

Number of potentially involved : 75,592

Estimated percentage with defect : 1

**Vehicle Information :**

Vehicle : 2015-2015 Jeep Cherokee

Vehicle Type :

Body Style : SUV

Power Train : NR

Descriptive Information : Certain MY 2015 Jeep Cherokee vehicles equipped with the 2.4L engine (Sales Code ED6 or ED8)

Production Dates : OCT 01, 2014 - JUN 18, 2015

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Some 2015 MY Jeep Cherokee ("KL") vehicles may experience a misrouted A/C suction/discharge combo line. A misrouted A/C combo line can be pinched and cut or thermally degraded by the exhaust manifold heat shield, potentially resulting in loss of air conditioning and the presence of smoke and/or fire.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : This defect may, in certain cases, result in smoke and/or fire.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

**Supplier Identification :**

**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

**Chronology :**

Please see the attached supplemental information titled "FCA US LLC Chronology - KL AC Line 10152015.pdf".

**Description of Remedy :**

Description of Remedy Program : Conduct a voluntary safety recall on all affected vehicles, to inspect for misrouted A/C suction discharge combo lines, and replace those found to be misrouted.

FCA US has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, FCA US, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the company for confirmation of the expense.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : 11/10/15: FCA US will provide dealer instructions on 11/16/15. Owner notification 11/23/15.\*\*

10/15/15: FCA US will provide a dealer notification and owner notification schedule once established.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

\* NR - Not Reported