

Part 573 Safety Recall Report

15V-713

Manufacturer Name : Newmar Corporation

Submission Date : MAY 06, 2016

NHTSA Recall No. : 15V-713

Manufacturer Recall No. : 15S25



Manufacturer Information :

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street

PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

Population :

Number of potentially involved : 93

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2016-2016 Newmar Bay Star Sport, Bay Star and Canyon Star

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the transmission selector lever cable bracket was manufactured out of specification causing the transmission selector lever cable to be installed incorrectly. This condition may result in unintended vehicle movement if force is applied to the transmission selector lever without first applying the brakes when in the park "P" position. Unintended vehicle movement may increase the risk of an injury or crash. Correction: Dealers are to replace the transmission shift cable bracket and adjust the shift cable.

Production Dates : JUL 08, 2015 - SEP 23, 2015

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : On certain motorhomes, the transmission selector lever cable bracket was manufactured out of specification causing the transmission selector lever cable to be installed incorrectly. This condition may result in unintended vehicle movement if force is applied to the transmission selector lever without first applying the brakes when in the park "P" position.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : This condition may result in unintended vehicle movement if force is applied to the transmission selector lever without first applying the brakes when in the park "P" position. Unintended vehicle movement may increase the risk of an injury or crash.

Description of the Cause : NR

Identification of Any Warning NR
that can Occur :

Supplier Identification :

Component Manufacturer

Name : Ford Motor Company
Address : NR
NR
Country : NR

Chronology :

10/23/ 2015; Newmar Corporation received notification of a potential equipment defect relating to motor vehicle safety that may exist in specific 2016 Ford F53 Chassis identified as potentially defective by Ford Motor Company.
10/28/2015 Newmar sent Notice of Defect to NHTSA

Description of Remedy :

Description of Remedy Program : Owners will be notified by mail and instructed to take their vehicles to a Ford Dealer to have the transmission shift control bracket replaced and the transmission shift cable adjusted. There will be no charge for this service.

How Remedy Component Differs NR
from Recalled Component :

Identify How/When Recall Condition NR
was Corrected in Production :

Recall Schedule :

Description of Recall Schedule : NR
Planned Dealer Notification Date : DEC 23, 2015 - NR
Planned Owner Notification Date : DEC 23, 2015 - NR

* NR - Not Reported