

Part 573 Safety Recall Report**15V-713****Manufacturer Name :** Newmar Corporation**Submission Date :** OCT 28,2015**NHTSA Recall No. :** 15V-713**Manufacturer Recall No. :** 15S25**Manufacturer Information :**

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street

PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

Population :

Number of potentially involved : 93

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2016-2016 Newmar Bay Star Sport, Bay Star and Canyon Star

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, the transmission selector lever cable bracket was manufactured out of specification causing the transmission selector lever cable to be installed incorrectly. This condition may result in unintended vehicle movement if force is applied to the transmission selector lever without first applying the brakes when in the park "P" position. Unintended vehicle movement may increase the risk of an injury or crash. Correction: Dealers are to replace the transmission shift cable bracket and adjust the shift cable.

Production Dates : JUL 08, 2015 -SEP 23, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

☐ Not sequential VINs**Description of Defect :**

Description of the Defect : On certain motorhomes, the transmission selector lever cable bracket was manufactured out of specification causing the transmission selector lever cable to be installed incorrectly. This condition may result in unintended vehicle movement if force is applied to the transmission selector lever without first applying the brakes when in the park "P" position.

FMVSS 1 :NR

FMVSS 2 :NR

Description of the Safety Risk : This condition may result in unintended vehicle movement if force is applied to the transmission selector lever without first applying the brakes when in the park "P" position. Unintended vehicle movement may increase the risk of an injury or crash.

Description of the Cause : NR
Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : Ford Motor Company

Address : NR

NR

Country : NR

Chronology :

NR

Description of Remedy :

Description of Remedy Program : Owners will be notified by mail and instructed to take their vehicles to a Ford Dealer to have the transmission shift control bracket replaced and the transmission shift cable adjusted. There will be no charge for this service.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : DEC 23, 2015 - NR

Planned Owner Notification Date : DEC 23, 2015 - NR

* NR - Not Reported