

Part 573 Safety Recall Report**15V-749****Manufacturer Name :** Winnebago Industries, Inc**Submission Date :** MAY 02, 2016**NHTSA Recall No. :** 15V-749**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Winnebago Industries, Inc

Address : PO BOX 152

605 W. Crystal Lake Rd. Forest City IA 50436

Company phone : 1-641-585-3535

Population :

Number of potentially involved : 3

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2008-2012 Winnebago Aspect and Vista

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : GAS

Descriptive Information : The motor vehicles potentially containing the defect were built between September 12, 2007 and February 15, 2012. The specific coaches involved were a 2008, WF726A Aspect, a 2010, WFE32K Vista, and a 2012, WFE36D Vista. These coaches were identified using the serial numbers provided by Ricon Corporation and production records showing the coach VIN

Production Dates : SEP 12, 2007 - FEB 15, 2012

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Winnebago Industries, Inc. has decided that defect which relates to motor vehicle safety exist on coaches built with certain Ricon wheel chair lifts. This decision was based on information provided by Ricon Corporation. Under certain conditions present in some application, the platforms included in the subject model wheelchair lifts can exhibit cracking of the platform pivot plate while in the stowed position which, if left unchecked, can propagate to the point where separation of the rear portion of the pivot plate occurs rendering the lift potentially inoperable and possibly unsafe for the operator. In the event that the aforementioned crack occurs on both sides, it is allowed to propagate to the point of material separation on both sides it is possible for the left platform to lean against the vehicle lift doors(s) and fall out of the vehicle when the door(s) is(are) opened putting the lift operator at risk

FMVSS 1 :NR

FMVSS 2 :NR

Description of the Safety Risk : If the lift is defective and leaning against the lift door(s) and the door(s) is(are) opened, the lift platform could fall from the coach causing bodily injury to a person(s) in close proximity to the lift.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : Ricon Corporation

Address : 1135 Aviation Place

San Fernando CALIFORNIA 91340

Country : United States

Chronology :

October 26, 2015 received Safety Recall Notice from Ricon. Recall appeared to be the same as recall 14V-586 made calls and E-mails to Ricon to confirm if this was a second notice of 14V-586. On November 6, 2015 Ricon confirmed that this was a new recall. November 6, 2015 Winnebago inputted notice on NHTSA Portal.

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported